

IDITAROD TRAIL INVENTORY

SITE CABIN AHRS NO: _____ INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:
 Seward-Rainy Pass X
 Rainy Pass-Kaltag
 Kaltag-Nome

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate _____ Actual X
 Quad. ANC 8-7
 Township T 14 N
 Range R 2 W *check 1W?*
 Section 17
 Subsection SW 1/4, SE 1/4
 Latitude: 61° 18' 5"
 Longitude: 149° 40' 30"

UTM REFERENCE:

A _____
 Zone _____ Easting _____ Northing _____

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
 Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	___	___	Dirt	Sod	Unknown
Log-Hewn	___	___	Wood	Metal	___
Frame	___	___	Other	Wd. Plank	___
Drop Siding	___	___	Unknown	Wd. Shingle	___
Wall Covering	___	___		Tar Paper	___
Unknown	___	___		Unknown	___

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- | | |
|--------------------------------|--------------|
| ___ Site Protection | ___ National |
| ___ Preservation/Stabilization | ___ Regional |
| ___ Restoration | ___ Local |
| ___ Reconstruction | |
| ___ Adaptive Reuse | |

Estimated Treatment Costs _____
 Estimated Planning/Research Costs _____

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
20 Medium
(1 Day Hike, Boat, Fixed-Wing)
40 ___ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 ___ No Remains
3 ___ Ruin
8 ___ Poor (Roof In)
15 ___ Medium (Roof Intact)
25 ___ Good (Maintained)
40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
___ Infrequent
 None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
10 ___ Medium
5 Low

Total Points 25

STATEMENT OF SIGNIFICANCE:

CABIN 10'd, GLO, 1917

REFERENCE:

GEN LAND OFFICE PLAT, JULY 18, 1917, DAVIDSON → 10'S CABIN & TRAIL SEG.

SITE RECOMMENDATIONS: