

SITE Rohn River #3 (Dog Barn) AHRS NO: McG-007 INHT NO: 220B-3

OTHER SITE NAMES:
Rohn River Roadhouse

TRAIL SECTION:
Seward-Rainy Pass
Rainy Pass-Kaltag X
Kaltag-Nome

LAND STATUS:
D-1 State Selection

LEGAL DESCRIPTION:
Approximate _____ Actual X
Quad. McGrath B-1
Township 26 N.
Range 22 W.
Section 33
Subsection _____

Latitude: 62 18' 00"
Longitude: 153 22' 00"

UTM REFERENCE:
A _____
Zone Easting Northing

LOCATION AND USE:

INSPECTED BY: Lynch (78) DATE: _____ Aerial _____ Onsite X
Peterson (80)

STRUCTURAL TYPE: Shelter Structure X River Community _____
Native Settlement _____ Mining Community _____ Other Dog Barn

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	<u>X</u>	<u>X</u>	Dirt <u>X</u>	Sod <u>X</u>	Unknown
Log-Hewn	_____	_____	Wood _____	Metal _____	Double Saddle
Frame	_____	_____	Other _____	Wd. Plank _____	Notch
Drop Siding	_____	_____	Unknown _____	Wd. Shingle _____	
Wall Covering	_____	_____		Tar Paper _____	
Unknown	_____	_____		Unknown _____	

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- X Regional
- _____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE Rohn River #3 (Dog Barn) AHRS NO: McG-007 INHT NO: 220B-3

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
20 Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 No Remains
3 Ruin
8 Poor (Roof In)
15 Medium (Roof Intact)
25 Good (Maintained)
40 Restored

PRESENT VISITOR USE

- Frequent
 Infrequent
 None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
10 Medium
5 Low

Total Points 43

STATEMENT OF SIGNIFICANCE:

Structure may date from 1910 and served as a large dog barn for use by mail carriers and local occupants.

The large enclosed dog barn found at many sites along the Iditarod Trail and perhaps along other northern trail systems represents a structure indigenous to the north and its use of the dog team.

REFERENCE:

SITE RECOMMENDATIONS:

1. Continued protection from natural fire and vandalism.
2. Include as part of a continued study of the dog barn along the trail.
3. Include as part of the site nomination to the National Register.
4. Stabilization; apply wood preservatives and remove vegetation.

1 SITE KOAN RIVER #3 (BURN) ARES NO: 1049-001 INHT NO. 200 B-3

2
3 OTHER SITE NAMES:
4 KOAN RIVER COMMUNITY
5
6
7

TRAIL SECTION -
- SEWARD - RAINY PASS ---
- RAINY PASS - KALTA
- KALTA - NONE ---

8
9 LAND STATUS:
10
11 B-1 STATE SELECTION

12 LEGAL DESCRIPTION:
13 APPROXIMATE --- ACTUAL
14 QUAD. McGREGOR B-1
15 TOWNSHIP 26 N
16 RANGE 22 W
17 SECTION 33
18 SUBSECTION

Handwritten scribble

19
20
21
22
23 LATITUDE: 60° 18' 00"
24 LONGITUDE: 153° 27' 00"

25
26 UTM REFERENCE:
27 A
28 ZONE EASTING NORTHING

29 LOCATION:

30
31
32
33 INSPECTED BY: LYNCH (76) PERKINS (60) DATE: AERIAL --- ONSITE

34
35 STRUCTURAL TYPE: SHELTER STRUCTURE RIVER COMMUNITY ---
36 NATIVE SETTLEMENT --- MINING COMMUNITY --- OTHER DOG BARN

37	38 WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
39	LOG-POUGH	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	DIRT <input checked="" type="checkbox"/>	SOD <input checked="" type="checkbox"/>	DOUBLE
40	LOG-HEWN	---	---	WOOD ---	METAL ---	SINGLE
41	FRAME	---	---	OTHER ---	WD PLANK ---	NOTCH
42	DROP SIDING	---	---		WD SHINGLE ---	
43	WALL COVERING	---	---		TAR PAPER ---	

44	TREATMENT RECOMMENDED	ORDER OF SIGNIFICANCE
45	--- PRESERVATION / STABILIZATION	--- NATIONAL
46	--- RESTORATION	<input checked="" type="checkbox"/> REGIONAL
47	--- RECONSTRUCTION	--- LOCAL
48	--- ADAPTIVE REUSE	

49
50 ESTIMATED TREATMENT COSTS _____
51 ESTIMATED PLANNING / RESEARCH COSTS _____
52

Handwritten signature

SITE: BEAN BARN #3 AHS NO 1000007 INHT NO. 220B-3

MANAGEMENT RATING CRITERIA

ACCESS — 40 POINTS

- 5 DIFFICULT
(DOG SLED, SNOWMOBIL, HELICOPTER)
- 20 MEDIUM
(1 DAY HIKE, BOAT, FIXED WING)
- 40 HIGH
(AUTO/ROAD, SHORT HIKE)

CONDITION — 40 POINTS

- NOT LOCATED
- 1 NO REMAINS
- 3 RUIN
- 8 POOR (ROOF IN)
- 15 MEDIUM (ROOF INTACT)
- 25 GOOD (MAINTAINED)
- 40 RESTORED

PHOTO

PRESENT VISITOR USE

- FREQUENT
- INFREQUENT
- NONE

POTENTIAL VISITOR USE — 20 POINTS

- 20 HIGH
- 10 MEDIUM
- 5 LOW

TOTAL POINTS 43

STATEMENT OF SIGNIFICANCE

NATION

STRUCTURE MAY DATE FROM 1910 AND SERVED AS A LARGE DOG BARN FOR USE BY MAIL CARRIERS AND LOCAL OCCUPANTS.

THE LARGE ENCLOSED DOGBARN FOUND AT MANY SITES ALONG THE IDITSOOD TRAIL AND PERHAPS ALONG OTHER NORTHERN TRAIL SYSTEMS REPRESENTS A STRUCTURE INDIGENOUS TO THE NORTH AND ITS USE OF THE DOG TEAM.

SITE RECOMMENDATIONS

1. CONTINUED PROTECTION FROM NATURAL FIRE AND VANDALISM.
2. INCLUDE AS PART OF A CONTINUED STUDY OF THE DOG BARN ALONG THE TRAIL.
3. INCLUDE AS PART OF THE SITE NOMINATION TO THE NATIONAL REGISTER
4. STABILIZATION; APPLY WOOD PRESERVATIVES, AND REMOVE VEGETATION.