

SITE SPRUCE CR. MINE AHRS NO: _____ INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass _____
Rainy Pass-Kaltag K
Kaltag-Nome _____

LAND STATUS:

MINE / ACTIVE → MIKE O'CALLAHAN OWNER

LEGAL DESCRIPTION:

Approximate _____ Actual _____
Quad. _____
Township _____
Range _____
Section _____
Subsection _____

Latitude: _____
Longitude: _____

UTM REFERENCE:

A _____
Zone Easting Northing

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	___	___	Dirt	Sod	Unknown
Log-Hewn	___	___	Wood	Metal	___
Frame	___	___	Other	Wd. Plank	___
Drop Siding	___	___	Unknown	Wd. Shingle	___
Wall Covering	___	___		Tar Paper	___
Unknown	___	___		Unknown	___

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- | | |
|--------------------------------|--------------|
| ___ Site Protection | ___ National |
| ___ Preservation/Stabilization | ___ Regional |
| ___ Restoration | ___ Local |
| ___ Reconstruction | |
| ___ Adaptive Reuse | |

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 ___ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
 - 1 ___ No Remains
 - 3 ___ Ruin
 - 8 ___ Poor (Roof In)
 - 15 Medium (Roof Intact)
 - 25 ___ Good (Maintained)
 - 40 ___ Restored
- } NOT INVENTORIED

PRESENT VISITOR USE

- ___ Frequent
- Infrequent
- ___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
- 10 Medium
- 5 ___ Low

Total Points 45

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS: