## Hydrogeologic Susceptibility and Vulnerability Assessment for The Laundry and Pioneer Pizza Drinking Water Well, Palmer, Alaska

DRINKING WATER PROTECTION PROGRAM REPORT 117

## Hydrogeologic Susceptibility and Vulnerability Assessment for The Laundry and Pioneer Pizza Drinking Water Well, Palmer, Alaska

By Michael Baxter, B.E.S.T. Resource

DRINKING WATER PROTECTION PROGRAM REPORT 117

ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION: 2001

#### **CONTENTS**

Page

Valley, Alaska The Laundry and Assessment/Prot	ne Ma a d Pio tectio	Page 1 Inventory of Potential and Existing 1 Contaminant Sources Ranking of Contaminant Risks 2 Vulnerability of The Laundry and Pioneer Pizza Drinking Water Source Summary Ng Water Source 3 References Cited	3	
		TABLES		
TABLE	1. 2. 3.	Natural Susceptibility - Susceptibility of the Wellhead and Aquifer to Contamination Contaminant Risks Overall Vulnerability of The Laundry and Pioneer Pizza Public Drinking Water Source to Contamination	4 4 5	
		ILLUSTRATIONS		
FIGURE	1.	Index map showing the location of Matanuska River Task Order Area		
		APPENDICES		
APPENDIX	В.	The Laundry and Pioneer Pizza Drinking Water Protection Area (Map 1) Contaminant Source Inventory for The Laundry and Pioneer Pizza (Table 1) Contaminant Source Inventory and Risk Ranking for The Laundry and Pioneer Pizza — Bacteria and Viruses (Table 2) Contaminant Source Inventory and Risk Ranking for The Laundry and Pioneer Pizza — Nitrates/Nitrites (Table 3) Contaminant Source Inventory and Risk Ranking for The Laundry and Pioneer Pizza — Volatile organic chemicals (Table 4) The Laundry and Pioneer Pizza Drinking Water Protection Area and Potential and Existing Contaminant Sources (Map 2) Vulnerability Analysis for Contaminant Source Inventory and Risk Ranking for The Laundry and Pioneer Pizza Public Drinking Water Source (Chart 1 – Chart 8 and Table 1 – Table 3)	g	

### Hydrogeologic Susceptibility and Vulnerability Assessment for The Laundry and Pioneer Pizza Public Drinking Water Source, Palmer, Alaska

By Michael Baxter, B.E.S.T. Resource

#### **Drinking Water Protection Program Alaska Department of Environmental Conservation**

#### **EXECUTIVE SUMMARY**

The The Laundry and Pioneer Pizza is a Class B (transient/noncommunity) drinking water source consisting of one well. Identified potential and current sources of contaminants for The Laundry and Pioneer Pizza include: a gas station with underground gas and diesel tanks, six roads, five septic systems and two residential acres. This identified potential and existing source of contamination is considered a source of bacteria and viruses, nitrates and/or nitrites, and volatile organic chemicals. Overall, The Laundry and Pioneer Pizza public water source received a vulnerability rating of **Low** for bacteria and viruses, **Medium** for nitrates and/or nitrites, and **High** volatile organic chemicals.




Figure 1. Index map showing the location of well assessment

#### INTRODUCTION

The purpose of this environmental assessment is to provide public water system owners/operators, communities, and local governments with information they can use to preserve the quality of Alaska's public drinking water supplies. This assessment was completed for The Laundry and Pioneer Pizza source of public drinking water. This source consists of one well

in the Palmer/Butte area (Figure 1). This assessment, known under the Alaska Drinking Water Protection Program as the *Source Water Assessment*, has combined a review of the natural hydrogeologic sensitivity with potential and existing contaminant risks to arrive at an overall vulnerability of the drinking water source to contamination. This assessment has been completed as a basis for local voluntary protection efforts and to assist agencies in their efforts to reduce risk to this public drinking water supply.

#### DESCRIPTION OF THE PALMER-AREA, ALASKA

#### Location

The Matanuska-Susitna Valley is part of the lowland lying about 50 miles north of Anchorage in south-central Alaska. The well described in this report is part of the Matanuska River Task Order Area. This study area is roughly bounded on the north by the Talkeetna Mountains; on the west by Wasilla Creek; on the south by the Knik River; and on the east by the Chugach Mountains. The area covers approximately 150 square miles.

#### Climate

The climate of the Matanuska-Susitna Valley is the result of a combination of marine and continental influences. The climate is somewhat transitional in that it does not experience large daily and annual temperature fluctuations like those experienced in the interior of Alaska nor does it experience high amounts of precipitation typified by gulf coast regions. Mean annual precipitation is approximately 15 inches per year. On the average, the Valley receives a total snow accumulation of 58 inches per year. Precipitation generally increased inland toward the Talkeetna Mountains where annual precipitation may exceed 60 inches per year [Barnwell, George, Dearborn, Weeks, and Zenone, 1972]. Mean daily temperature ranges from 67° F during July to 5° F in January [Western Regional Climate Center, 2000].

#### **Physiography and Groundwater Conditions**

The Matanuska-Susitna Valley is surrounded by rugged mountains that rise abruptly from the valley floor. The Chugach Mountains at the southern edge of the valley reach altitudes greater than 6300 feet. These mountains are composed primarily of metamorphosed sedimentary marine and volcanic rocks, and greenstone of Mesozoic age. Along the northern edge of the valley peaks in the Talkeetna Mountains reach altitudes of 3000 to 5000 feet. The Talkeenta Mountains are composed mainly of igneous rocks, chiefly granitic intrusives (Mesozoic?) and subordinate lavas and tuffs; Cretaceous and Tertiary sedimentary rocks form the south flank of the mountains. Although the altitude of the valley floor ranges from sea level at Knik Arm to 1000 feet at the base of Wishbone Hill, the local relief is commonly not more than 100 to 200 feet.

The area is drained by the Matanuska and Knik Rivers. These rivers are braided glacial outwash streams having wide floodplains. Drainage is poor in many interstream tracts resulting in large areas of swampy ground with shallow lakes occupying depressions.

The Matanuska-Susitna Valley is floored with unconsolidated deposits, chiefly glacial drift, that represents several episodes of glacial advances and retreats. The drift includes till, outwash stream deposits, and estuarine and lake deposits. Physiographic features formed by these deposits in or adjacent to the study area include end moraine, lateral moraines, eskers, crevasses fillings, and other pitted features, river terraces, outwash floodplains and an extensive estuarine flat.

The glacial till and bedrock form aquifers of minor importance. The chief hydrologic significance of the till is in confining the artesian aquifer. Generally, the till is poorly permeable, although locally thin layers of sand may yield small quantities of water. Till that is present at or near the land surface in much of the area makes the acquisition of shallow groundwater difficult. The bedrock also is poorly permeable. It yields water only from fractures, whose location and frequency cannot be easily predicted.

The chief aquifers are composed of outwash sand and gravel laid down by melt-water streams or in lakes. The outwash deposits are of two chief forms. The first consists of sheetlike deposits that lie just beneath the ground surface. These deposits range in thickness from a few feet to more than 100 feet. They typically rest on till of bedrock. The water in these deposits is unconfined. The other outwash deposits are buried beneath till. They are known to be as much as 50 to 60

feet thick, and probably are considerably thicker in some places. They commonly contain confined, or artesian, groundwater. Well logs and data from pumping tests suggest that outwash sand and gravel form a continuous or nearly continuous sheet in an area of more than 10 square miles north and west of Palmer.

Recharge of the groundwater is chiefly from precipitation but it is likely that only a small proportion of the annual precipitation reaches the water body. During very dry seasons conspicuous declines in of water levels occur in many wells. Along the mountain fronts, groundwater seeps from fractures in bedrock into the sediments. At these higher elevations, rain and snowmelt also enter the sediments. Lastly, aguifers may be recharged by streams where surface water percolates into surrounding permeable sediments (losing reaches of streams). This is the case for the water-table aquifers in the terrace south of Palmer and in the Bodenberg Butte area, which receive underground flow from the Matanuska River. Groundwater flow in the confined aguifers is generally from the north and northnorthwest. The direction of groundwater flow in the upper unconfined aquifer is more variable due to the influence from surficial topography as well as its close connection with surface water bodies.

#### THE LAUNDRY AND PIONEER PIZZA PUBLIC WATER SOURCE

The Laundry and Pioneer Pizza public water source is a Class B (transient/noncommunity) water source, which is privately owned and operated. The source consists of one well near the base of the Chugach Mountains and is at an elevation of 350 feet above sea level. The well is located on the southeast end of Bodenburg Butte; at the intersection of Marth and the Glenallen highway. According to the well log, The Laundry and Pioneer Pizza grouting is unknown, but is functioning properly. The well penetrates gravel and silty sand 80 feet below land surface. The well's screening is unknown, but the static water level was 40 feet on 9/28/84 the day of drilling.

The water from The Laundry and Pioneer Pizza consists of hydropneumatic pressure tanks, jet pump and atmospheric storage tanks. This water source operates year round. The The Laundry and Pioneer Pizza drinking water source collectively serves approximately 25 residents and non-residents through four service connections.

## ASSESSMENT AND PROTECTION AREA FOR THE LAUNDRY AND PIONEER PIZZA DRINKING WATER SOURCE

The Drinking Water Protection and Assessment Area that has been established for The Laundry and Pioneer Pizza is the area that is most sensitive to contamination. This area has served as a basis for assessing the risk of the drinking water source to contamination. This zone around the drinking water source is the most critical area for the preservation of the quality of the drinking water for this source. For simplicity, this area will be known as your Drinking Water Protection Area and will serve as the area of focus for voluntary protection efforts.

Conceptually, groundwater enters the aquifer systems along the front range of the Talkeetna and Chugach Mountains and flows toward Cook Inlet. An analytical calculation was used to calculate the size and shape of the area that contributes water to the well. The input parameters describing the attributes of the aquifer in this calculation were adopted from the U.S. Geological Survey (Patrick, Brabets, and Glass, 1989). This analytical calculation was used as a guide as the first step in establishing the protection area for The Laundry and Pioneer Pizza. Additional methods were further employed to take into account any uncertainties in groundwater flow and aquifer characteristics to arrive at a meaningful and conservative protection area with respect to public health (Please refer to the Guidance Manual for Class B Public Water Systems for additional information).

The Drinking Water Protection Areas established for wells by the Alaska Department of Environmental Conservation (ADEC) are separated into zones. These zones correspond to a time-of-travel. Time-of-travel is the time required for water to move in the saturated zone of the ground from a specific point to the well. The Drinking Water Protection Areas for The Laundry and Pioneer Pizza contain four zones, Zone A, Zone B, Zone C and Zone D (See Map 1 in Appendix A). Zone A corresponds to the area between the well and the distance equal to \( \frac{1}{4} \) of the distance of the 2-year timeof-travel. Depending on where a contaminant source is located within Zone A, travel time for a contaminant to the well may be on the order of several days to several hours. Zone A also extends down gradient from the well to take into account the area of the aguifer that is influenced by pumping of the well.

The Zone B protection area for The Laundry and Pioneer Pizza corresponds to a time-of-travel of less than two years and extends toward to base of the Chugach Mountains. Lastly, the Zone C protection area extends from Zone B to Zone D, which extends north paralleling the Matanuska River and heading towards the Chugach Mountains.

#### INVENTORY OF POTENTIAL AND EXISTING CONTAMINANT SOURCES

The Drinking Water Protection Program has completed an inventory of potential and existing sources of contamination within The Laundry and Pioneer Pizza Drinking Water Protection Area. This survey was completed through a search of ADEC records and other publicly available information.

Potential sources of contamination to drinking water supplies cover a wide range of categories and types. Potential drinking water contaminants are found within agricultural, residential, commercial, and industrial areas, but can also occur within areas that have little or no development.

For the basis of this assessment and all Class B public water system assessments, three categories of drinking water contaminants were inventoried. They include:

- Bacteria and viruses;
- Nitrates and/or nitrites;
- Volatile organic chemicals;

Map 1 in Appendix C depicts the Contaminant Source Inventory for The Laundry and Pioneer Pizza. Inventoried potential sources of contamination within Zones A through Zone B were associated with residential activity. Zones C & D contains only natural wilderness. On account of natural wilderness in Zones C & D, this potential source of contamination was not considered in determining the vulnerability of this drinking water source to contamination. Below is a summary of the contaminant sources inventoried within The Laundry and Pioneer Pizza protection area:

- Residential acreage
- Gas Station with underground gas and diesel tanks
- Roads
- Septic systems
- Contaminated site:

This potential contaminant source presents risks for all three categories of drinking water contaminants for The Laundry and Pioneer Pizza drinking water source.

#### RANKING OF CONTAMINANT RISKS

Potential and existing sources of contamination have been identified, sorted, and ranked according to what type and level of risk they represent. Ranking of contaminant risks for a "potential" or "existing" source of contamination is a function of toxicity and volumes of specific contaminants associated with that source. Contaminant risks are further a function of the number and density of those types of contaminant sources as well as the proximity of those sources to the well.

#### VULNERABILITY OF THE LAUNDRY AND PIONEER PIZZA DRINKING WATER SOURCES

Vulnerability of a drinking water source to contamination is a combination of two factors:

- natural susceptibility; and
- contaminant risks.

Each of the three categories of drinking water contaminants has been analyzed and an overall vulnerability score of 0 to 100 is ultimately assigned:

Natural Susceptibility (0 - 50 points)

+

Contaminant Risks (0 - 50 points)

=

Vulnerability of the Drinking Water Source to Contamination (0 - 100).

A score for the Natural Susceptibility is achieved by analyzing the properties of the well and the aquifer.

Susceptibility of the Wellhead (0-25 Points)+
Susceptibility of the Aquifer (0-25 Points)

= Natural Susceptibility (Susceptibility of the Well) (0-50 Points)

The Laundry and Pioneer Pizza is completed in an unconfined aquifer setting. The well penetrates 80 feet of sand and gravel layers. These layers may provide somewhat of a protective barrier for the movement of contaminants in the subsurface. However, near the base of the Chugach and Talkeetna Mountains, the clay and till layers tend to be discontinuous and thin toward the mountains. Therefore, contaminants that enter the subsurface near the base of the mountains may enter the confined aquifer uninhibited by the absence of any protective layer. This well does not appear to be properly grouted as indicated previously from information obtained from ADEC records. The absence of grouting can promote the transport of contaminants

along the well casing. Combining the susceptibility of the wellhead and the aquifer to contamination leads to a score (0-50 points) and rating of overall Susceptibility (See Appendix D). Table 1 shows the overall Susceptibility score and rating for The Laundry and Pioneer Pizza.

Table 1. Natural Susceptibility - Susceptibility of the Wellhead and Aquifer to Contamination

	Score	Rating
Susceptibility of the Wellhead	10	Medium
Susceptibility of the Aquifer	17	High
Natural Susceptibility	27	Medium

Contaminant risks to a drinking water source depend on the type, number or density, and distribution of contaminant sources. One gas station with underground gas and diesel tanks, roads, septic systems, a ADEC contaminated site and domestic lawns and gardens contribute the highest identified risks for potential contamination to The Laundry and Pioneer Pizza source of public drinking water.

A score (0-50 points) and rating of Contaminant Risks (See Appendix D) is assigned based on the findings of the Contaminant Source Inventory (Appendix B - Table 1-Table 7). This portion of the analysis examines any existing or historical contamination that has been detected at the drinking water source through routine sampling. It also reviews contamination that has or may have occurred but has not arrived or been detected at the well. Table 2 summarizes the Contaminant Risks for each category of drinking water contaminants.

**Table 2. Contaminant Risks** 

Score	Rating
12	Low
13	Low
45	Very High
	12 13

Appendix D contains eight charts, which together form the 'Vulnerability Analysis' for a source water assessment for a public drinking water source. Chart 1 analyzes the 'Susceptibility of the Wellhead' to contamination by looking at the construction of the well and its surrounding area. Chart 2 analyzes the 'Susceptibility of the Aquifer' to contamination by looking at the naturally occurring attributes of the water source and influences on the groundwater system that

might lead to contamination. Chart 3 analyzes 'Contaminant Risks' for the drinking water source with respect to bacteria and viruses. The 'Contaminant Risks' portion of the analysis considers potential sources of contaminants as well as a review of contamination that has or may have occurred but has not arrived or been detected at the well. Lastly, Chart 4 contains the 'Vulnerability Analysis for Bacteria and Viruses'. Charts 5 through 8 contain the Contaminant Risks and Vulnerability Analysis for nitrates and nitrites and volatile organic chemicals, respectively.

Vulnerability of the drinking water source to contamination is the combination of susceptibility of the aquifer and the well with contaminant risks. Table 3 contains the overall vulnerability scores (0-100) and ratings for each of the three categories of drinking water contaminants (See Appendix D). Note: scores are rounded off to the nearest five.

Table 3. Overall Vulnerability of The Laundry and Pioneer Pizza Public Drinking Water Source to Contamination by Category

Category	Score	Rating
Bacteria and Viruses	30	Low
Nitrates and Nitrites	40	Medium
Volatile Organic Chemicals	70	High

Tables 2 through 4 in Appendix B contain the ranking of potential and existing sources of contamination with respect to bacteria and viruses, nitrates and/or nitrites, and volatile organic chemicals.

The roads and septic systems in Zone A are the factors determining contaminant risks for all categories of contaminants (See "Overall Rank after Analysis" in Table 2-4 of Appendix B).

Bacteria and Viruses were not detected in the source waters of The Laundry and Pioneer Pizza. Overall, contaminant risk for the bacteria and viruses is low due to the roads, septic systems, gas station with underground storage tanks and an ADEC recognized contaminated site. This rating combined with the susceptibility of the well yields an overall low vulnerability to contamination in this category.

Sampling history of The Laundry and Pioneer Pizza source waters indicate concentrations of nitrate (See Chart 6 – Contaminant Risks for Nitrates/Nitrites in Appendix D). Existing nitrate contamination is approximately 2% of the allowable limit (MCL) for this contaminant. Due to the high solubility and weak

retention by soil, nitrates are very mobile in soil, moving at approximately the same rate as water. The current nitrate concentration in The Laundry and Pioneer Pizza remains at safe levels with respect to human health.

Overall, contaminant risk for the nitrate/nitrite category is low due to the roads, septic systems, gas station with underground storage tanks and an ADEC recognized contaminated site present up gradient from the well. Combining potential nitrate and/or nitrite contamination risk with the susceptibility of the well yields an overall medium vulnerability to contamination in this category.

Volatile Organic Chemicals were not detected in the source waters of The Laundry and Pioneer Pizza. Overall, a contaminant risk for the volatile organic chemicals category is high due to the roads, septic systems, gas station with underground storage tanks and an ADEC recognized contaminated site present up gradient from the well. Combining the contaminate risk with the susceptibility of the well yields an overall high vulnerability to contamination for Volatile Organic Chemicals.

#### **SUMMARY**

A Source Water Assessment has been completed for The Laundry and Pioneer Pizza source of public drinking water. The overall vulnerability of this source to contamination is **Low** for bacteria and viruses, **Medium** for nitrates and/or nitrites, and **High** for volatile organic chemicals. This assessment of contaminant risks can be used as a foundation for local voluntary protection efforts as well as a basis for the continuous efforts on the part of The Laundry and Pioneer Pizza to protect public health. It is anticipated that Source Water Assessments will be updated every five years to reflect any changes in the vulnerability and/or susceptibility of the public drinking water source.

#### REFERENCES CITED

Jakola, J.B., Munter, J.A., and Evans, J.G., 1991, Ground-water resources of the Palmer-big Lake area, Alaska: a conceptual model. Division of Geological & Geophysical Surveys Reported of Investigations 90-4, State of Alaska Department of Natural Resources, Fairbanks, AK.

Trainer, F.W., 1960, Geology and Groundwater Resources, Matanuska Valley, Alaska, U.S. Geological Survey Water Supply Paper 1494 U.S. Printing Office, Washington, D.C.


Western Regional Climate Center, 2000, August 24, Web extension to the *Western Regional Climate Center* 

[WWW document]. URL http://www.uaa.alaska.edu/enri/ascc web/ascc home.html .

#### **APPENDIX A**

The Laundry and Pioneer Pizza Drinking Water Protection Area

## The Laundry and Pioneer Pizza (PWSID 227663) Drinking Water Protection Areas



#### **APPENDIX B**

Contaminant Source Inventory and Risk Ranking for The Laundry and Pioneer Pizza

#### Contaminant Source Inventory for The Lundry and Pioneer Pizza

Contaminate Source Category	Contaminant Source ID	CS ID Tag	Zone	Location	Мар	Comments
Septic systems (serves one or more single-family homes)	R2	R2-1	A	Fraggle Rock CT	2	
Septic systems (serves one or more single-family homes)	R2	R2-2	С	Back Acres	2	
Septic systems (serves one or more single-family homes)	R2	R2-3	С	Back Acres	2	
Septic systems (serves one or more single-family homes)	R2	R2-4	С	Back Acres	2	
Septic systems (serves one or more single-family homes)	R2	R2-5	С	Back Acres	2	
Highways and roads, dirt/gravel	X24	X24-1	A	Fraggle Rock CT	2	
Highways and roads, dirt/gravel	X24	X24-2	A	Marilyn	2	
Highways and roads, dirt/gravel	X24	X24-3	A	Marth	2	
Highways and roads, dirt/gravel	X24	X24-4	A	Back Acres	2	
Highways and roads, dirt/gravel	X20	X20-1	A,B	Old Glenn Highway	2	
Gasoline Station (without repair shop)	C15	C15-1	A	Old Glenn Highway	2	
Underground Gasoline Storage Tank	T12	T12-1	A	Old Glenn Highway	2	
Underground Diesel Storage Tank	Т8	T8-1	A	Old Glenn Highway	2	
Contaminated Site	U4	U4-1	A	Old Glenn Highway	2	Previously leaky underground storage tank; site closed
Lawn & Garden	R1	R1-1	С	Back Acres	2	Contains 2 acres

#### Potential and Existing Sources of Contamination for The Lundry and Pioneer Pizza Bacterias and Viruses

<b>Contaminant Source Category</b>	Contaminant Source ID	CS ID Tag	Zone	Risk Ranking for Analysis	Overall Rank for	Location	Map	Comments
Septic systems (serves one or more single-family homes)	R2	R2-1	A	Very Low	1	Fraggle Rock CT	2	
Highways and roads, dirt/gravel	X24	X24-1	A	Very Low	2	Fraggle Rock CT	2	
Highways and roads, dirt/gravel	X24	X24-2	A	Very Low	3	Marilyn	2	
Highways and roads, dirt/gravel	X24	X24-3	A	Very Low	4	Marth	2	
Highways and roads, dirt/gravel	X24	X24-4	A	Very Low	5	Back Acres	2	
Highways and roads, dirt/gravel	X20	X20-1	A,B	Very Low	6	Old Glenn Highway	2	
Septic systems (serves one or more single-family homes)	R2	R2-2	С	Very Low	7	Back Acres	2	
Septic systems (serves one or more single-family homes)	R2	R2-3	С	Very Low	8	Back Acres	2	
Septic systems (serves one or more single-family homes)	R2	R2-4	С	Very Low	9	Back Acres	2	
Septic systems (serves one or more single-family homes)	R2	R2-5	С	Very Low	10	Back Acres	2	
Lawn & Garden	R1	R1-1	С	Low		Back Acres	2	Contains 2 acres
Gasoline Station (without repair shop)	C15	C15-1	A	Very Low		Old Glenn Highway	2	
Underground Gasoline Storage Tank	T12	T12-1	A	Very Low		Old Glenn Highway	2	
Underground Diesel Storage Tank	Т8	T8-1	A	Very Low		Old Glenn Highway	2	
Contaminated Site	U4	U4-1	A	Very Low		Old Glenn Highway	2	Previously leaky underground storage tank; site closed

#### Potential and Existing Sources of Contamination for The Laundry and Pioneer Pizza Nitrates and Nitrites

Contaminant Source Category	Contaminant Source ID	CS ID Tag	Zone	Risk Ranking for	Overall Rank for	Location	Map	Comments
Septic systems (serves one or more single-family homes)	R2	R2-1	A	Very Low	1	Fraggle Rock CT	2	
Highways and roads, dirt/gravel	X24	X24-1	A	Very Low	2	Fraggle Rock CT	2	
Highways and roads, dirt/gravel	X24	X24-2	A	Very Low	3	Marilyn	2	
Highways and roads, dirt/gravel	X24	X24-3	A	Very Low	4	Marth	2	
Highways and roads, dirt/gravel	X24	X24-4	A	Very Low	5	Back Acres	2	
Highways and roads, dirt/gravel	X20	X20-1	A,B	Very Low	6	Old Glenn Highway	2	
Septic systems (serves one or more single-family homes)	R2	R2-2	С	Very Low	7	Back Acres	2	
Septic systems (serves one or more single-family homes)	R2	R2-3	С	Very Low	8	Back Acres	2	
Septic systems (serves one or more single-family homes)	R2	R2-4	С	Very Low	9	Back Acres	2	
Septic systems (serves one or more single-family homes)	R2	R2-5	С	Very Low	10	Back Acres	2	


#### Potential and Existing Sources of Contamination for The Laundry and Pioneer Pizza Volatile Organic Chemicals (VOCs)

Contaminant Source Category	Contaminant Source ID	CS ID Tag	Zone	Risk Ranking for	Overall Rank for	Location	Map	Comments
Gasoline Station (without repair shop)	C15	C15-1	A	High	1	Old Glenn Highway	2	
Underground Gasoline Storage Tank	T12	T12-1	A	High	2	Old Glenn Highway	2	
Underground Diesel Storage Tank	Т8	T8-1	A	High	3	Old Glenn Highway	2	
Contaminated Site	U4	U4-1	A	Low	4	Old Glenn Highway	2	Previously leaky underground storage tank; site closed
Septic systems (serves one or more single-family homes)	R2	R2-1	A	Very Low	5	Fraggle Rock CT	2	
Highways and roads, dirt/gravel	X24	X24-1	A	Very Low	6	Fraggle Rock CT	2	
Highways and roads, dirt/gravel	X24	X24-2	A	Very Low	7	Marilyn	2	
Highways and roads, dirt/gravel	X24	X24-3	A	Very Low	8	Marth	2	
Highways and roads, dirt/gravel	X24	X24-4	A	Very Low	9	Back Acres	2	
Highways and roads, dirt/gravel	X20	X20-1	А,В	Very Low	10	Old Glenn Highway	2	
Septic systems (serves one or more single-family homes)	R2	R2-2	С	Very Low		Back Acres	2	
Septic systems (serves one or more single-family homes)	R2	R2-3	С	Very Low		Back Acres	2	
Septic systems (serves one or more single-family homes)	R2	R2-4	С	Very Low		Back Acres	2	
Septic systems (serves one or more single-family homes)	R2	R2-5	С	Very Low		Back Acres	2	
Lawn & Garden	R1	R1-1	С	Low		Back Acres	2	Contains 2 acres

#### **APPENDIX C**

The Laundry and Pioneer Pizza
Drinking Water Protection Area
and Potential & Existing Contaminant Sources

# Drinking Water Protection Areas Potential & Existing Sources of Contamination for The Laundry and Pioneer Pizza





Tanks, diesel (underground)

(T8)

Tanks, gasoline (underground)

- (T12)
  Previously leaky
- underground storage tank (U4)
  Gasoline station (without
- repair shop) (C15)
  Residential Well & Septic
- Systems (R2)
- Lawn & Garden (R1)
- Mat-Su Borough Parcels

Roads (Paved X20) (Gravel X24)

/ Elevation contours

- Public Water System Well
- Zone A Protection Area
- Zone B Protection Area
- Zone C Protection Area

Map 2

#### **APPENDIX D**

Vulnerability Analysis for The Laundry and Pioneer Pizza Public Drinking Water Source

Chart 1. Susceptibility of the wellhead – The Laundry and Pioneer Pizza




Chart 2. Susceptibility of the aquifer – The Laundry and Pioneer Pizza




Chart 3. Contaminant risks for The Laundry and Pioneer Pizza – Bacteria & Viruses




Chart 3. Contaminant risks for The Laundry and Pioneer Pizza – Bacteria & Viruses (Continued)





Chart 3. Contaminant risks for The Laundry and Pioneer Pizza – Bacteria & Viruses (Continued)



#### Level of Risk Associated with the Highest Risk Sources

1 residential septic system, 4 roads	LOW 10 pts	MEDIUM 20 pts	HIGH 30 pts	VERY HIGH 40 pts
Low	≥ 10 sources + 10 pts	≥ 10 sources + 5 pts	≥ 20 sources + 5 pts	
Medium	_	≥ 2 sources + 5 pts	≥ 5 sources + 5 pts	≥ 10 sources + 5 pts
High			1 source + 10 pts	≥ 2 sources + 10 pts
Very High				1 source + 10 pts

Next Highest Risk Sources(s)

Chart 4. Vulnerability analysis for The Laundry and Pioneer Pizza- Bacteria & Viruses




Chart 5. Contaminant risks for The Laundry and Pioneer Pizza- Nitrates and Nitrites




Chart 5. Contaminant risks for The Laundry and Pioneer Pizza-Nitrates and Nitrites (Continued)





Chart 5. Contaminant risks for The Laundry and Pioneer Pizza–Nitrates and Nitrites (Continued)



#### Level of Risk Associated with the Highest Risk Sources

1 residential septic system, 5 roads and 2 residential acres	LOW 10 pts	MEDIUM 20 pts	HIGH 30 pts	VERY HIGH 40 pts
Low	> 10 sources + 10 pts	> 10 sources + 5 pts	> 20 sources + 5 pts	
Medium		> 2 sources + 5 pts	> 5 sources + 5 pts	> 10 sources + 5 pts
High			1 source + 10 pts	> 2 sources + 10 pts
Very High				1 source + 10 pts

Next Highest Risk Sources(s)

Chart 6. Vulnerability analysis for The Laundry and Pioneer Pizza-Nitrates and Nitrites




Chart 7. Contaminant risks for The Laundry and Pioneer Pizza – Volatile Organic Chemicals




Chart 7. Contaminant risks for The Laundry and Pioneer Pizza – Volatile Organic Chemicals (Continued)





Chart 7. Contaminant risks for The Laundry and Pioneer Pizza – Volatile Organic Chemicals (Continued)



#### Table 3. Risk Matrix for Contaminant Sources for The Laundry and Pioneer Pizza – Volatile Organic Chemicals

#### Level of Risk Associated with the Highest Risk Sources

1 residential septic system, 5 roads, 2 residential acres, 1 gas station, 1 underground gas tank, and 1 underground diesel tank, 1 contaminated site	LOW 10 pts	MEDIUM 20 pts	HIGH 30 pts	VERY HIGH 40 pts
Low	> 10 sources + 10 pts	> 10 sources + 5 pts	> 20 sources + 5 pts	
Medium		> 2 sources + 5 pts	> 5 sources + 5 pts	> 10 sources + 5 pts
High			1 source + 10 pts	> 2 sources + 10 pts
Very High				1 source + 10 pts

Chart 8. Vulnerability analysis for The Laundry and Pioneer Pizza- Volatile Organic Chemicals

