Estimated Planning/Research Costs

SITE Rohn River Site #1	AHRS	NO:
MANAGEMENT RATING CRITERIA		48
ACCESS 40 POINTS		
5 Difficult		
(Dog Sled, Snow Mach., Heli.)		
20 X Medium		
(1 Day Hike, Boat, Fixed-Wing)		
40 High		
(Auto/Road, Short Hike)		
CONDITION 40 POINTS		
Not Located		
1 No Remains		
3 Ruin		
8 Poor (Roof In)		*
15 Medium (Roof Intact)		
$25 \times Good$ (Maintained)		
40 Restored		
PRESENT VISITOR USE		
Frequent		
X Infrequent		
None		
POTENTIAL VISITOR USE20 POINTS		
20 X High		
10 Medium		

65

STATEMENT OF SIGNIFICANCE:

Low

Total Points

Constructed in 1910 as a result of Goodwin's 1910 survey of the Iditarod Trail. It served for many years, with many owners, as a primary roadhouse stop on the trail.

Cabin #1 - Constructed in 1924, rebuilt 1929 - assumed use was that of a relief cabin and trapper's cabin - continues as such today.

REF: Goodwin 1908 and 1910, Cadwallader 1917 and 1919, Reed 1920, 1923 American Geographic Society - Iditarod Historic Trail files.

MEMISON MILL Shows RP CHMP #47 Same LOCATION

ROLL PIVER, RUBY RECORD CITIZEN, DER BIPNO

ROLL RIVER (VOLGER'S) MARIA, 11914, RUBY RECORP CITIZEN

CAPWALLDPER, 1917 10'S RHONE RIVER ROADHOUSE OWNED BY RICHBRED'S BROTHERS

ALC GATETTEER & DIRECTORY, 1915-1916 -> 10'S ROLL RIVER BUD INDICATED THAT THORE WAS NO BOAPHOUSE

REFERENCE: LETTER BY ED BY ER, FEB 25, 1911, 10'S A'D "BIG JOHN'S"

McG-007

200B #1

INHT NO:

Lynch, Alice J., 1979. A Preliminary Inventory of Cultural Resources of the Iditarod Trail Between Rainy Pass and Unalakleet. Bureau of Land Management. Peterson, Steven M., 1980. Site Survey and Recordation.

SITE RECOMMENDATIONS:

- 1. Continued protection and maintenance as a shelter cabin and Iditarod Race Support Cabin.
- 2. Nominate to the National Register of Historic Places.
- 3. Suggested stabilization program replace sod roof, apply wood preservatives to structure, repair chimney, sash and trim and remove vegetation as fire protective measure.