	AHRS NO:	INHT NO:
OTHER SITE NAMES:	TRAIL SECTION:  Seward-Rainy Pass Rainy Pass-Kaltag Kaltag-Nome	<u> </u>
AND STATUS:	- -	
EGAL DESCRIPTION:	_	
Approximate Quad. Township Range Range	-	
Section 15 Subsection CONTER		
Latitude: 60° - 47' 00" Longitude: 149° - 32' 30"		
UTM REFERENCE: A	Northing	· · · · · · · · · · · · · · · · · · ·
	<u> </u>	
LOGOTED AT THE DUNISTION	OF THE JOHNSON 7	RAIL AWD
LOCATED AT THE JUNCTION LANYON CREEK TRAIL (THE TE	OF THE JOHNSON TO	RAIL AWD  TARY RAP IN THE  Onsite
LANYON CREEK TRAIL (THE TELL AREA) OF MICHELON'S LAGINED INSPECTED BY:  STRUCTURAL TYPE: Shelter Str	DATE: Aerial	TARY RAP IN THE  Onsite  munity
LOGDTED AT THE JUNCTION  LANYON CREEK TRAIL (THE TEX  AREA OF MICHELON'S LAGIN  INSPECTED BY:  STRUCTURAL TYPE: Shelter Str  Native Settlement Mir  WALLS: IN OUT FLOOT  Log-Rough Di  Log-Hewn Wo  Frame Ot	DATE: Aerial	TARY RAP IN THE  Onsite  munity
LOGDTED AT THE JUNCTION  LANYON CREEK TRAIL (THE TRAIL  ARED OF MICHELSON'S LAGIN'S  INSPECTED BY:  STRUCTURAL TYPE: Shelter Str  Native Settlement Min  WALLS: IN OUT FLOO  Log-Rough Di  Log-Hewn Wo  Frame Ot  Drop Siding Un  Wall Covering	DATE: Aerial  Fucture River Comming Community Other  OR ROOF  Irt Sod  ood Metal  ther Wd. Plank  oknown Wd. Shingle  Tar Paper	Onsite  Onsite  CORNER NOTCH  Unknown

SITE	AHRS NO:	
MANAGEMENT RATING CRITERIA		
ACCESS 40 POINTS		
5 Difficult		
(Dog Sled, Snow Mach., Heli.)		
20 Medium		
(1 Day Hike, Boat, Fixed-Wing)		
40 X High		
(Auto/Road, Short Hike)		
CONDITION 40 POINTS		
Not Located		
1 X No Remains		
3 Ruin		
8 Poor (Roof In)		
15Medium (Roof Intact)		
25 Good (Maintained)		
40 Restored		
PRESENT VISITOR USE		
★ Frequent		
Infrequent		•
None		
POTENTIAL VISITOR USE20 POINTS		
20 High		
10 Medium		

STATEMENT OF SIGNIFICANCE:

Total Points 46

Confluence of the two rivers near the Bruhn-Rey Mines and the Gunetien of the Ophrson's Pass Viail with the Conjunce (Moore Pass train).

INHT NO:

5 X Low

P.H. SLEEM'S IMAP OF THE KENDI MINING DISTRICT, 1910

## SITE RECOMMENDATIONS: