

Source Water Assessment

A Hydrogeologic Susceptibility and Vulnerability Assessment for Alaskan View Motel Public Drinking Water System, Wasilla, Alaska PWSID # 225572.001

DRINKING WATER PROTECTION REPORT 1669

Alaska Department of Environmental Conservation

January, 2009

Source Water Assessment for Alaskan View Motel Public Drinking Water System Wasilla, Alaska PWSID# 225572.001

DRINKING WATER PROTECTION REPORT 1669

The Drinking Water Protection (DWP) section of the Drinking Water Program is producing Source Water Assessments in compliance with the Safe Drinking Water Act Amendments of 1996. Each assessment includes a delineation of the source water area, an inventory of potential and existing contaminant sources that may impact the water, a risk ranking for each of these contaminants, and an evaluation of the potential vulnerability of these drinking water sources.

These assessments are intended to provide public water systems owners/operators, communities, and local governments with the best available information that may be used to protect the quality of their drinking water. The assessments combine information obtained from various sources, including the U.S. Environmental Protection Agency, Alaska Department of Environmental Conservation (DEC), public water system owners/operators, and other public information sources. The results of this assessment are subject to change if additional data becomes available. It is anticipated this assessment will be updated every five years to reflect any changes in the vulnerability and/or susceptibility of public drinking water source. If you have any additional information that may affect the results of this assessment, please contact the DWP staff at the following toll-free number 1-866-956-7656.

CONTENTS

		Page	Page
	nmary	1 Ranking of Contaminant Risks	2
Alaskan View	Motel	Vulnerability of Alaskan View Motel	
Public Drinkin	g Water System	1 Drinking Water System	2
Alaskan View	Motel	References	5
Drinking Wate	er Protection Area	1 Appendix A	7
Inventory of Po	otential and	Appendix B	9
Existing Conta	nminant Sources	2 Appendix C	11
		TABLES	
Table 4. Overa	ill Vulnerability		3
	A	PPENDICES	
APPENDIX	A. Alaskan View Motel Drinkin	ng Water Protection Area (Map A)	
		ry for Alaskan View Motel (Table 1)	
	Contaminant Source Inven Viruses (Table 2)	tory and Risk Ranking for Alaskan View Motel – I	Bacteria and
	Contaminant Source Inven (Table 3)	tory and Risk Ranking for Alaskan View Motel – I	Nitrates/Nitrites
	Contaminant Source Inven Chemicals (Table 4)	tory and Risk Ranking for Alaskan View Motel – `	Volatile Organic
	C. Alaskan View Motel Drink Sources (Map C)	ing Water Protection Area and Potential and Exist	ting Contaminant

Source Water Assessment for

Alaskan View Motel Source of Public Drinking Water, Big Wasilla, Alaska

Drinking Water Protection Alaska Department of Environmental Conservation

EXECUTIVE SUMMARY

The public water system for Alaskan View Motel is a Class B (transient/non-community) water system consisting of one well located on the Parks Highway in Wasilla, Alaska. The wellhead received a susceptibility rating of Verv High and the aguifer received a susceptibility rating of Very High. Combining these two ratings produces a Very High rating for the natural susceptibility of the well. Identified potential and current sources of contaminants for Alaskan View Motel public drinking water source include: assumed septic systems, assumed heating oil tanks, roads, a body shop, a car dealership, a sewerline, an industrial process water and wastewater well, a medical/veterinary facility, a furniture manufacturer, a park, and Open Leaking Underground Fuel Storage Tank (LUST) sites. These identified potential and existing sources of contamination are considered as sources of bacteria and viruses, nitrates and/or nitrites, and volatile organic chemicals. Overall, the public water sources for Alaskan View Motel received a vulnerability rating of Very High for all three contaminant categories. This assessment of contaminant risks can be used as a foundation for local voluntary protection efforts as well as a basis for the continuous efforts on the part of Alaskan View Motel to protect public health.

ALASKAN VIEW MOTEL PUBLIC DRINKING WATER SYSTEM

The Alaskan View Motel public water system is a Class B (transient/non-community) water system. The system consists of one well located on the Parks Highway in Wasilla, Alaska (see Map A in Appendix A). Wasilla, with a population of 7,028, lies about 12 miles north of the Knik Arm of Cook Inlet along the George Parks Highway.

The majority of residents in the Wasilla area have individual wells and septic systems, but the city does operate a water and sewer system. Homes are heated by piped natural gas, provided by Enstar. Refuse is transported by a private firm to the Borough landfill (ADCCED, 2009).

Due to the glacial influence in the formation of the Wasilla area, the landforms in Wasilla are made up of ridges of glacial till and flat benches of gravel and sand out wash (Matanuska-Susitna Borough, 1985). The

altitude of the Wasilla area ranges from about 300 feet to 500 feet above sea level, gradually sloping downwards towards Cook Inlet. There are hundreds of small lakes in the area, several larger lakes, and two large streams (Renshaw Consulting Engineers, 1983).

According to the well log (07/25/1996), the well extends approximately 426 feet below the ground surface and is completed in a confined aquifer. This system operates from April to September and serves 46 non-residents through one service connection.

ALASKAN VIEW MOTEL DRINKING WATER PROTECTION AREA

In order to evaluate whether a drinking water source is at risk, we must first evaluate what are the most likely pathways for surface contamination to reach the groundwater. These areas are determined by looking at the characteristics of the soil, groundwater, aquifer, and well.

The most probable area for contamination to reach the drinking water well is the drinking water protection area. The drinking water protection area is the area circling the well (the area influenced by pumping) and also the area upgradient of the well, usually forming a parabola shape. Because releases of contaminants within the protection area are most likely to impact the well, this area will serve as the focus for voluntary protection efforts.

There are many different methods for calculating the size of protection areas. Drinking Water Protection (DWP) uses a combination of two simple groundwater flow equations, the Thiem and uniform flow equations for all groundwater wells screened in unconsolidated material. The orientation of the protection zone is then drawn using a water table elevation map (if available) or a land surface elevation map of the area. The protection zone calculated by DWP is an estimate using the available information and resources, and may differ slightly from the actual capture zone. Because of uncertainties and changing site conditions, a factor of safety is added to the protection zone to form the drinking water protection area for the well.

The parameters used to calculate the shape of this protection zone are general for the whole alluvial plain and were obtained from various United States

Geological Survey (USGS) reports, area well logs, and the Groundwater textbook by Freeze and Cherry (Freeze and Cherry, 1979).

The protection areas established for wells by the DEC are usually separated into two zones, limited by the watershed. These zones correspond to differences in the time-of-travel (TOT) of the water moving through the aquifer to the well. An analytical calculation was used to determine the size and shape of the protection area.

The time-of-travel for contaminants within the water varies and is dependent on the physical and chemical characteristics of each contaminant. The following is a summary of the two protection area zones for wells and the calculated time-of-travel for each:

Table 1. Definition of Zones

Zone	Definition
A	Several months time-of-travel
В	Less than the 2 year time-of-travel

The drinking water protection area for Alaskan View Motel was determined using an analytical calculation and includes Zones A and B (See Map A of Appendix A).

INVENTORY OF POTENTIAL AND EXISTING CONTAMINANT SOURCES

DWP has completed an inventory of potential and existing sources of contamination within the Alaskan View Motel drinking water protection area. This inventory was completed through a search of agency records and other publicly available information. Potential sources of contamination to the drinking water aquifer include a wide range of categories and types. Potential drinking water contaminants are found within agricultural, residential, commercial, and industrial areas, but can also occur within areas that have little or no development.

For the basis of all Class B public water system assessments, the following three categories of drinking water contaminants were inventoried:

- Bacteria and viruses:
- Nitrates and/or nitrites;
- Volatile organic chemicals

The sources are displayed on Map C of Appendix C and summarized in Table 1 of Appendix B.

RANKING OF CONTAMINANT RISKS

Once the potential and existing sources of contamination have been identified, they are assigned a ranking according to what type and level of risk they represent. Ranking of contaminant risks for a

"potential" or "existing" source of contamination is a function of toxicity and volumes of specific contaminants associated with that source. Rankings include:

- Low:
- Medium:
- High; and
- Very High.

Tables 2 through 4 in Appendix B contain the ranking of potential and existing sources of contamination with respect to bacteria and viruses, nitrates and/or nitrites, and volatile organic chemicals.

VULNERABILITY OF ALASKAN VIEW MOTEL DRINKING WATER SYSTEM

Vulnerability of a drinking water source to contamination is a combination of two factors:

- Natural Susceptibility; and
- Contaminant Risks.

A score for the Natural Susceptibility of the well is reached by considering the properties of the well and the aquifer.

Susceptibility of the Wellhead (0-25 Points)

+
Susceptibility of the Aquifer (0-25 Points)

-

Natural Susceptibility of the Well (0-50 Points)

A ranking is assigned for the Natural Susceptibility according to the point score:

Natural Susceptibility Ratings		
40-50 pts	Very High	
30 to < 40 pts	High	
20 to < 30 pts	Medium	
< 20 pts	Low	

Factors contributing to the susceptibility of the wellhead are: whether the sanitary seal is in place, protection from flooding, and if the well casing is properly grouted.

The wellhead for the Alaskan View Motel received a **Very High** susceptibility rating. The most recent sanitary survey (03/05/2004) indicates that the sanitary seal is broken, the land surface is sloped away from the well, and the status of grouting is unknown. Sanitary seals prevent potential contaminants from entering the well while sloping of the land surface and grouting help to prevent potential contaminants from traveling down the outside of the well casing.

Factors contributing to the susceptibility of the aquifer are: whether the aquifer is confined or unconfined, whether the well is completed in unconsolidated or fractured bedrock, whether wells and bore holes are penetrating the aquifer and, if applicable, the confining layer.

The Alaskan View Motel system draws water from a confined aquifer overlain by 49 feet of hardpan and clay layers. It received a **Very High** susceptibility rating because of the presence of other wells that penetrate the vadose zone within the protection area. Other wells penetrating the vadose zone of the protection area can allow contaminants to travel into the shared aquifer with precipitation and runoff.

Table 2 summarizes the Susceptibility scores and ratings for the Alaskan View Motel system.

Table 2. Susceptibility

	Score	Rating
Susceptibility of the	20	Very High
Wellhead		
Susceptibility of the	20	Very High
Aquifer		
Natural Susceptibility	40	Very High

Contaminant risks are derived from an evaluation of the routine sampling results of the water system and the presence of potential sources of contamination.

Contaminant risks to a drinking water source depend on the type and distribution of contaminant sources. Flow charts are used to assign a point score, and ratings are assigned in the same way as for the natural susceptibility:

Contaminant Risk Ratings			
40-50 pts	Very High		
30 to < 40 pts	High		
20 to < 30 pts	Medium		
< 20 pts	Low		

Table 3 summarizes the Contaminant Risks for each category of drinking water contaminants for the Alaskan View Motel system.

Table 3. Contaminant Risks

Category	Score	Rating
Bacteria and Viruses	40	Very High
Nitrates and/or Nitrites	50	Very High
Volatile Organic Chemicals	45	Very High

Finally, an overall vulnerability score is assigned for each water system by combining each of the contaminant risk scores with the natural susceptibility score:

Natural Susceptibility (0-50 Points)
+
Contaminant Risks (0-50 Points)

Vulnerability of the Drinking Water Source to Contamination (0-100 Points)

Again, rankings are assigned according to a point score:

Overall Vulnerability Ratings		
80-100 pts	Very High	
60 to < 80 pts	High	
40 to < 60 pts	Medium	
< 40 pts	Low	

Table 4 contains the overall vulnerability scores (0-100) and ratings for each of the three categories of drinking water contaminants for the Alaskan View Motel system. Note: scores are rounded off to the nearest five.

Table 4. Overall Vulnerability

Category	Score	Rating
Bacteria and Viruses	80	Very High
Nitrates and/or Nitrites	90	Very High
Volatile Organic Chemicals	85	Very High

Bacteria and Viruses

The contaminant risk for bacteria and viruses is **Very High** with assumed septic systems, roads, a sewerline, an industrial process water and wastewater well, a medical/veterinary facility, and a park contributing to the risk to the drinking water well.

Coliforms (a bacteria) are found naturally in the environment and although they aren't necessarily a health threat, they are an indicator of other potentially harmful bacteria in the water, more specifically, fecal coliforms and E. coli, which only come from human and animal fecal waste. Harmful bacteria can cause diarrhea, cramps, nausea, headaches, or other symptoms (EPA, 2008).

Only a small amount of bacteria and viruses are required to endanger public health. Positive samples increase the overall vulnerability of the drinking water source, indicating that the source is susceptible to bacteria and virus contamination. Bacteria and viruses have not recently been detected during water sampling of the system at Alaskan View Motel (data reviewed in April, 2008).

After combining the contaminant risk for bacteria and viruses with the natural susceptibility of the well, the overall vulnerability of the well to contamination is **Very High**.

Nitrates and Nitrites

The contaminant risk for nitrates and nitrites is **Very High** with assumed septic systems, roads, a sewerline, an industrial process water and wastewater well, a medical/veterinary facility, and a park contributing to the risk to the drinking water well.

The sampling history for the Alaskan View Motel well indicates that nitrates have been detected in the water within the last 5 years, with the highest concentration of 4.08 mg/l detected on 12/29/2005 (data reviewed in April, 2008).

After combining the contaminant risk for nitrates and nitrites with the natural susceptibility of the well, the overall vulnerability of the well to contamination is **Very High**.

Volatile Organic Chemicals

The contaminant risk for volatile organic chemicals is **Very High** with assumed septic systems, assumed heating oil tanks, roads, a body shop, a car dealership, a sewerline, an industrial process water and wastewater well, a medical/veterinary facility, and a furniture manufacturer contributing to the risk to the drinking water well.

The water system at Alaskan View Motel has not recently been sampled for volatile organic chemicals (data reviewed in April, 2008).

After combining the contaminant risk for volatile organic chemicals with the natural susceptibility of the well, the overall vulnerability of the well to contamination is **Very High**.

Using the Source Water Assessment

This assessment of contaminant risks can be used as a foundation for local voluntary protection efforts as well as a basis for the continuous efforts on the part of Alaskan View Motel to protect public health. It is anticipated that Source Water Assessments will be updated every five years to reflect any changes in the vulnerability and/or susceptibility of Alaskan View Motel drinking water source.

REFERENCES

Alaska Department of Commerce, Community and Economic Development (ADCCED), Accessed 2009 [WWW document]. URL: http://www.commerce.state.ak.us/dca/commdb/CF_COMDB.htm

Freeze, R.A. and Cherry, J.A., 1979. Groundwater. Prentice-Hall, Englewood Cliffs, NJ.

Matanuska-Susitna Borough, 1985, Knik-Matanuska-Sisitna: A Visual History of the Valleys, Wasilla, AK.


Renshaw Consulting Engineers, 1983, Summary of Mineral Resources, Palmer, AK.

United States Environmental Protection Agency (EPA), Accessed 2008 [WWW document]. URL: http://www.epa.gov/safewater/contaminants/index.html.

APPENDIX A

Alaskan View Motel Drinking Water Protection Area Location Map (Map A)

Public Water Well System for PWS #225572.001 Alaskan View Motel



<u>Legend</u>

Class B Public Water System Well

Groundwater Protection Zones

Zone A Protection Area - Several Months Travel Time



Zone B Protection Area - 2 Years Travel Time


Data Sources:

Contaminant Sources, Public Water System Wells, Alaska Department of Environmental Conservation (ADEC)

All other data: Alaska Statewide Digital Mapping Initiative (SDMI)

Drinking Water Protection Areas based on "Alaska Drinking Water Protection Program - Guidance Manual for Class B Public Water Systems" published by ADEC

URS Corporation does not guarantee the accuracy or validity of the data provided.







Miles 0.5

Alaskan View Motel PWS 225572.001

Appendix A Map A

APPENDIX B

Contaminant Source Inventory and Risk Ranking for Alaskan View Motel (Tables 1-4)

Contaminant Source Inventory for ALASKAN VIEW MOTEL

Contaminant Source Type	Contaminant Source ID	CS ID tag	Zone	Map Number	Comments
Body shops (automotive)	C05	C05-01	A	С	
Motor vehicle dealerships - cars, trucks, motor cycles, ATV's, snow machines, boats (with service department)	C27	C27-01	A	С	
Domestic wastewater collection systems (sewer lines or lift stations)	D01	D01	A	С	1 sewerline
Injection wells (Class V) Industrial Process Water & Water Disposal Wells	D40	D40-01	A	С	
Septic systems (serves one single-family home)	R02	R02	A	С	3 assumed septic systems
Tanks, heating oil, residential (above ground)	R08	R08	A	C	3 assumed heating oil tanks
Open Leaking Underground Fuel Storage Tank (LUST) Sites	U07	U07-01	A	С	
Closed Leaking Underground Fuel Storage Tank (LUST) Sites	U08	U08-01	A	С	
Highways and roads, paved (cement or asphalt)	X20	X20	A	С	1 road
Medical/veterinary facilities (doctor or dentist offices, hospitals, nursing homes)	X40	X40-01	A	С	
Furniture manufacturing, repair, and finishing shops	C14	C14-01	В	С	
Domestic wastewater collection systems (sewer lines or lift stations)	D01	D01	В	С	1 sewerline
Septic systems (serves one single-family home)	R02	R02	В	С	20 assumed septic systems
Tanks, heating oil, residential (above ground)	R08	R08	В	С	20 assumed heating oil tanks
Municipal or city parks (with green areas)	X04	X04	В	С	
Highways and roads, paved (cement or asphalt)	X20	X20	В	С	3 roads

Contaminant Source Inventory and Risk Ranking for ALASKAN VIEW MOTEL

Sources of Bacteria and Viruses

Contaminant Source Type	Contaminant Source ID	CS ID tag	Zone	Risk Ranking for Analysis	Map Number	Comments
Domestic wastewater collection systems (sewer lines or lift stations)	D01	D01	A	Medium	С	1 sewerline
Injection wells (Class V) Industrial Process Water & Water Disposal Wells	D40	D40-01	A	High	C	
Septic systems (serves one single-family home)	R02	R02	A	Low	C	3 assumed septic systems
Highways and roads, paved (cement or asphalt)	X20	X20	A	Low	С	1 road
Medical/veterinary facilities (doctor or dentist offices, hospitals, nursing homes)	X40	X40-01	A	Medium	С	
Domestic wastewater collection systems (sewer lines or lift stations)	D01	D01	В	Medium	С	1 sewerline
Septic systems (serves one single-family home)	R02	R02	В	Low	C	20 assumed septic systems
Municipal or city parks (with green areas)	X04	X04	В	Medium	С	
Highways and roads, paved (cement or asphalt)	X20	X20	В	Low	С	3 roads

Contaminant Source Inventory and Risk Ranking for ALASKAN VIEW MOTEL

Sources of Nitrates/Nitrites

Contaminant Source Type	Contaminant Source ID	CS ID tag	Zone	Risk Ranking for Analysis	Map Number	Comments
Domestic wastewater collection systems (sewer lines or lift stations)	D01	D01	A	Medium	С	1 sewerline
Injection wells (Class V) Industrial Process Water & Water Disposal Wells	D40	D40-01	A	High	С	
Septic systems (serves one single-family home)	R02	R02	A	Low	C	3 assumed septic systems
Highways and roads, paved (cement or asphalt)	X20	X20	A	Low	С	1 road
Medical/veterinary facilities (doctor or dentist offices, hospitals, nursing homes)	X40	X40-01	A	Low	С	
Domestic wastewater collection systems (sewer lines or lift stations)	D01	D01	В	Medium	С	1 sewerline
Septic systems (serves one single-family home)	R02	R02	В	Low	C	20 assumed septic systems
Municipal or city parks (with green areas)	X04	X04	В	Medium	С	
Highways and roads, paved (cement or asphalt)	X20	X20	В	Low	С	3 roads

Contaminant Source Inventory and Risk Ranking for ALASKAN VIEW MOTEL


Sources of Volatile Organic Chemicals

Contaminant Source Type	Contaminant Source ID	CS ID tag	Zone	Risk Ranking for Analysis	Map Number	Comments
Body shops (automotive)	C05	C05-01	A	Medium	С	
Motor vehicle dealerships - cars, trucks, motor cycles, ATV's, snow machines, boats (with service department)	C27	C27-01	A	Medium	С	
Domestic wastewater collection systems (sewer lines or lift stations)	D01	D01	A	Low	С	1 sewerline
Injection wells (Class V) Industrial Process Water & Water Disposal Wells	D40	D40-01	A	High	С	
Septic systems (serves one single-family home)	R02	R02	A	Low	C	3 assumed septic systems
Tanks, heating oil, residential (above ground)	R08	R08	A	Medium	C	3 assumed heating oil tanks
Highways and roads, paved (cement or asphalt)	X20	X20	A	Low	C	1 road
Medical/veterinary facilities (doctor or dentist offices, hospitals, nursing homes)	X40	X40-01	A	Low	С	
Furniture manufacturing, repair, and finishing shops	C14	C14-01	В	Medium	C	
Domestic wastewater collection systems (sewer lines or lift stations)	D01	D01	В	Low	С	1 sewerline
Septic systems (serves one single-family home)	R02	R02	В	Low	C	20 assumed septic systems
Tanks, heating oil, residential (above ground)	R08	R08	В	Medium	С	20 assumed heating oil tanks
Highways and roads, paved (cement or asphalt)	X20	X20	В	Low	С	3 roads

APPENDIX C

Alaskan View Motel
Drinking Water Protection Area
and Potential and Existing Contaminant Sources
(Map C)

Public Water Well System for PWS # 225572.001 Alaskan View Motel Showing Potential and Existing Sources of Contamination



500

1,000

<u>Legend</u>

- Class A Public Water System
- Class B Public Water System

Groundwater Protection Zones

Z

Zone A Protection Area - Several Months Travel Time



Zone B Protection Area - 2 Years Travel Time

Potential or Contaminant Sources

- Body shops (automotive) (C05)
 - Furniture manufacturing, repair, and finishing shops (C14)
 - Motor vehicle dealerships (with service department) C27)
- Injection wells (Class V) Industrial Process Water & Water Disposal Wells (D40)
- Open Leaking Underground Fuel Storage Tank (LUST) Sites (U07)
- Closed Leaking Underground Fuel Storage Tank (LUST) Sites (U08)
- Medical/veterinary facilities (doctor or dentist offices, hospitals, nursing homes) (X40)

Data Sources:


Contaminant Sources, Public Water System Wells, Alaska Department of Environmental Conservation (ADEC)

All other data:

Alaska Statewide Digital Mapping Initiative (SDMI)

Drinking Water Protection Areas based on "Alaska Drinking Water Protection Program - Guidance Manual for Class B Public Water Systems" published by ADEC

URS Corporation does not guarantee the accuracy or validity of the data provided.







2,000

Alaskan View Motel PWS 225572.001

Appendix C Map C