

SITE MCDUGAL ROADHOUSE AHRS NO: TYO-047 INHT NO: \_\_\_\_\_

OTHER SITE NAMES: \_\_\_\_\_

TRAIL SECTION:  
Seward-Rainy Pass X  
Rainy Pass-Kaltag \_\_\_\_\_  
Kaltag-Nome \_\_\_\_\_

LAND STATUS: \_\_\_\_\_

LEGAL DESCRIPTION:

Approximate \_\_\_\_\_ Actual X  
Quad. TYO  
Township T 21 N  
Range R 9 W  
Section 14  
Subsection SW 1/4, SW 1/4

Latitude: 61° 54' 30"  
Longitude: 150° 42' 40"

UTM REFERENCE:

A \_\_\_\_\_  
Zone \_\_\_\_\_ Easting \_\_\_\_\_ Northing \_\_\_\_\_

LOCATION AND USE:

N. SIDE OF YENTNA RIVER, ± 1 MILE WEST OF MOUTH OF LAKE CREEK

INSPECTED BY: \_\_\_\_\_ DATE: \_\_\_\_\_ Aerial \_\_\_\_\_ Onsite \_\_\_\_\_

STRUCTURAL TYPE: Shelter Structure X River Community X  
Native Settlement \_\_\_\_\_ Mining Community \_\_\_\_\_ Other \_\_\_\_\_

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: \_\_\_\_\_ ORDER OF SIGNIFICANCE: \_\_\_\_\_

- \_\_\_\_\_ Site Protection
- \_\_\_\_\_ Preservation/Stabilization
- \_\_\_\_\_ Restoration
- \_\_\_\_\_ Reconstruction
- \_\_\_\_\_ Adaptive Reuse
- \_\_\_\_\_ National
- \_\_\_\_\_ Regional
- \_\_\_\_\_ Local

Estimated Treatment Costs \_\_\_\_\_  
Estimated Planning/Research Costs \_\_\_\_\_

IDITAROD TRAIL INVENTORY

SITE \_\_\_\_\_ AHRS NO: \_\_\_\_\_ INHT NO: \_\_\_\_\_

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 \_\_\_ Difficult  
(Dog Sled, Snow Mach., Heli.)  
20  Medium  
(1 Day Hike, Boat, Fixed-Wing)  
40 \_\_\_ High  
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located  
1 \_\_\_ No Remains  
3 \_\_\_ Ruin  
8 \_\_\_ Poor (Roof In)  
15 \_\_\_ Medium (Roof Intact)  
25 \_\_\_ Good (Maintained)  
40 \_\_\_ Restored

PRESENT VISITOR USE

- \_\_\_ Frequent  
 Infrequent  
\_\_\_ None

POTENTIAL VISITOR USE--20 POINTS

- 20 \_\_\_ High  
10  Medium  
5 \_\_\_ Low

Total Points 30

STATEMENT OF SIGNIFICANCE:

AEC, 1914 - 10'S 3 STRUCTURES AT MCPHERSON

REFERENCE:

AEC KUSKOKWIM RECONNAISSANCE, ~~J. L. McPHERSON~~ J. L. McPHERSON, DEC 1914

SITE RECOMMENDATIONS: