SITE	BAHRENBERG CABIN	AHRS NO:	INHT NO:	
OTHER	SITE NAMES:	TRAIL SECTION: Seward-Rainy Pass Rainy Pass-Kaltag Kaltag-Nome) PA
LAND	STATUS:			O E
	DESCRIPTION: Approximate x Actual Quad. Township TIIN Range £2E Section 9			NVENT
	Subsection Latitude: 61° 65° 40" Longitude: 149° 07° 60° UTM REFERENCE: A Zone Easting TON AND USE:	Northing		RAIL I
INSPE	CTED BY:	DATE: Aerial _	Onsite	F
	WALLS: IN OUT FLOOR	ing Community Other	erCORNER NO	
	Log-Rough Dir Log-Hewn Woo Frame Oth Drop Siding Unk Wall Covering Unknown	od Metal	Unknown	ITAR
TREAT	MENT RECOMMENDED:	ORDER OF SIGNIFICA		
	Site Protection Preservation/Stabilization Restoration Reconstruction Adaptive Reuse	on National Regional Local		ID
	Estimated Treatment Costs Estimated Planning/Research Co	osts		

SITE	AHRS NO:	INHT NO:
MANAGEMENT RATING CRITERIA		
ACCESS 40 POINTS		
5 Difficult		
(Dog Sled, Snow Mach., Heli.)		
20 X Medium		
(1 Day Hike, Boat, Fixed-Wing)		
40 High		
(Auto/Road, Short Hike)		
CONDITION 40 POINTS		
Not Located		
1No Remains		
3Ruin		
8 Poor (Roof In)		
15 X Medium (Roof Intact)		
25Good (Maintained)		
40Restored		
PRESENT VISITOR USE		
Frequent		
<u>X</u> Infrequent		
None		
POTENTIAL VISITOR USE-20 POINTS		
20 High		
10 × Medium		
5Low		
Total Points 45		

STATEMENT OF SIGNIFICANCE:

REFERENCE:

CARBERRY, MUHAEL E., PATTERN'S OF THE PAGE, (MUNICIPALITY OF ANCHORAGE), JAN 1979

SITE RECOMMENDATIONS: