

IDITAROD TRAIL INVENTORY

1914
 SITE CABIN AHRS NO: _____ INHT NO: _____

OTHER SITE NAMES: _____ TRAIL SECTION:
 Seward-Rainy Pass X
 Rainy Pass-Kaltag _____
 Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:
 Approximate _____ Actual X
 Quad. ANC B-8
 Township T16N
 Range R2W
 Section 19
 Subsection NW¹/₄, SW¹/₄, SE¹/₄, SW¹/₄
 Latitude: 61° 28' 00"
 Longitude: 149° 42' 40"

UTM REFERENCE:
 A _____
 Zone _____ Easting _____ Northing _____

LOCATION AND USE: _____

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
 Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- | | |
|----------------------------------|----------------|
| _____ Site Protection | _____ National |
| _____ Preservation/Stabilization | _____ Regional |
| _____ Restoration | _____ Local |
| _____ Reconstruction | |
| _____ Adaptive Reuse | |

Estimated Treatment Costs _____
 Estimated Planning/Research Costs _____

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
20 Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 No Remains
3 Ruin
8 Poor (Roof In)
15 Medium (Roof Intact)
25 Good (Maintained)
40 Restored

PRESENT VISITOR USE

- Frequent
 Infrequent
 None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
10 Medium
5 Low

Total Points 25

STATEMENT OF SIGNIFICANCE:

REFERENCE:

GEN. LAND OFF PLAT, NOV 23, 1914, DAVIDSON → LOCATES

SITE RECOMMENDATIONS: