

SITE SHEEP CR. CABIN

AHRS NO: MCG-020

INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass _____

Rainy Pass-Kaltag X

Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate	Actual	X
Quad.	<u>MCG</u>	_____
Township	<u>T 31N</u>	_____
Range	<u>R 28W</u>	_____
Section	<u>14</u>	_____
Subsection	<u>NW, SE</u>	_____

Latitude: 67° 46' 32.55"

Longitude: 154° 28' 12.51"

UTM REFERENCE:

A _____
 Zone Easting Northing

LOCATION AND USE: _____

INSPECTED BY: _____

DATE: _____

Aerial _____ Onsite _____

STRUCTURAL TYPE:

Shelter Structure _____ River Community _____

Native Settlement _____ Mining Community _____ Other CABIN

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	<u>X</u>	<u>X</u>	Dirt _____	Sod _____	Unknown <u>X</u>
Log-Hewn	_____	_____	Wood _____	Metal _____	
Frame	_____	_____	Other _____	Wd. Plank <u>X</u>	
Drop Siding	_____	_____	Unknown <u>X</u>	Wd. Shingle _____	
Wall Covering	_____	_____		Tar Paper _____	
Unknown	_____	_____		Unknown _____	

TREATMENT RECOMMENDED: _____

ORDER OF SIGNIFICANCE: _____

- | | |
|----------------------------------|----------------|
| <u>X</u> Site Protection | _____ National |
| _____ Preservation/Stabilization | _____ Regional |
| _____ Restoration | _____ Local |
| _____ Reconstruction | |
| _____ Adaptive Reuse | |

Estimated Treatment Costs _____

Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
20 Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 No Remains
3 Ruin
8 Poor (Roof In)
15 Medium (Roof Intact)
25 Good (Maintained)
40 Restored

PRESENT VISITOR USE

- Frequent
 Infrequent
 None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
10 Medium
5 Low

Total Points 28

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS: