

SITE Rohn River Structure #1 AHRS NO: McG-007 INHT NO: 200B #1

OTHER SITE NAMES:

Rohn Roadhouse

Rohn River Roadhouse (Goodwin 1910/11)

TRAIL SECTION:

Seward-Rainy Pass

Rainy Pass-Kaltag X

Kaltag-Nome

LAND STATUS:

D-1 State Selection

Air Navigation Site Withdrawal

LEGAL DESCRIPTION:

Approximate	Actual
Quad.	<u>McGrath B-1</u>
Township	<u>26 N</u>
Range	<u>22 W.</u>
Section	<u>33</u>
Subsection	<u> </u>

Latitude: 62 18' 00"

Longitude: 153 22' 00"

UTM REFERENCE:

A Zone Easting Northing

LOCATION AND USE:

Periodic use as a shelter cabin.

INSPECTED BY: Lynch (78) DATE: Aerial Onsite X
 Peterson (80)

STRUCTURAL TYPE: Shelter Structure X River Community
 Native Settlement Mining Community Other

<u>WALLS:</u>	<u>IN</u>	<u>OUT</u>	<u>FLOOR</u>	<u>ROOF</u>	<u>CORNER NOTCH</u>
Log-Rough	<u>X</u>	<u>X</u>	Dirt <u> </u>	Sod <u> </u> <u>X</u>	Unknown
Log-Hewn	<u> </u>	<u> </u>	Wood <u> </u> <u>X</u>	Metal <u> </u>	Double Saddle
Frame	<u> </u>	<u> </u>	Other <u> </u>	Wd. Plank <u> </u>	Notch
Drop Siding	<u> </u>	<u> </u>	Unknown <u> </u>	Wd. Shingle <u> </u>	
Wall Covering	<u> </u>	<u> </u>		Tar Paper <u> </u>	
Unknown	<u> </u>	<u> </u>		Unknown <u> </u>	

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

 Site Protection
X Preservation/Stabilization
 Restoration
 Reconstruction
 Adaptive Reuse

 National
X Regional
 Local

Estimated Treatment Costs
 Estimated Planning/Research Costs

IDITAROD TRAIL INVENTORY

SITE Rohn River Site #1 AHRS NO: McG-007 INHT NO: 200B #1

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
20 Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 No Remains
3 Ruin
8 Poor (Roof In)
15 Medium (Roof Intact)
25 Good (Maintained)
40 Restored

PRESENT VISITOR USE

- Frequent
 Infrequent
 None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
10 Medium
5 Low

Total Points 65

STATEMENT OF SIGNIFICANCE:

Constructed in 1910 as a result of Goodwin's 1910 survey of the Iditarod Trail. It served for many years, with many owners, as a primary roadhouse stop on the trail.

Cabin #1 - Constructed in 1924, rebuilt 1929 - assumed use was that of a relief cabin and trapper's cabin - continues as such today.

REF: Goodwin 1908 and 1910, Cadwallader 1917 and 1919, Reed 1920, 1923 American Geographic Society - Iditarod Historic Trail files.

REFERENCE:

- Lynch, Alice J., 1979. A Preliminary Inventory of Cultural Resources of the Iditarod Trail Between Rainy Pass and Unalakleet. Bureau of Land Management.
Peterson, Steven M., 1980. Site Survey and Recordation.

SITE RECOMMENDATIONS:

1. Continued protection and maintenance as a shelter cabin and Iditarod Race Support Cabin.
2. Nominate to the National Register of Historic Places.
3. Suggested stabilization program - replace sod roof, apply wood preservatives to structure, repair chimney, sash and trim and remove vegetation as fire protective measure.

1 SITE RAIN RIVER STRUCTURE #1 AHS NO: MCQ-001 INHT NO. 200B#1

2
3 OTHER SITE NAMES:

- 4 • RAIN ROADHOUSE
- 5 • RAIN RIVER BR - GORWIN 1910/11

TRAIL SECTION -

- SEWARD - RAIN PASS ---
- RAINY PASS - KALTAG -X-
- KALTAG - NOME ---

9 LAND STATUS:

10 D-T STATE SELECTION,
11 AIR NAVIGATION SITE
12
13
14

15 LEGAL DESCRIPTION:

16 APPROXIMATE --- ACTUAL ---
 17 QUAD. MCGRATH #1
 18 TOWNSHIP 26 N
 19 RANGE 22 W
 20 SECTION 33
 21 SUBSECTION ---

Handwritten scribble: 11/27/00

22 LATITUDE: 62° 19' 00"

23 LONGITUDE: 153° 22' 00"

26 UTM REFERENCE:

27 A --- --- ---
28 ZONE EASTING NORTHING

29 LOCATION:

31
32
33 INSPECTED BY: LYNCH (78) PETERSON (80) RATE AERIAL --- ONSITE X

35 STRUCTURAL TYPE: SHELTER STRUCTURE X RIVER COMMUNITY ---
36 NATIVE SETTLEMENT --- MINING COMMUNITY --- OTHER ---

37	38 WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
39	LOG-POUGH	X	X	DIRT	SOD	X Double
40	LOG-HEWN	---	---	WOOD	METAL	SADDLE
41	FRAME	---	---	OTHER	WD. PLANK	NOTCH
42	DROP SIDING	---	---		WD. SHINGLE	
43	WALL COVERING	---	---		TAR PAPER	

45 TREATMENT RECOMMENDED ORDER OF SIGNIFICANCE:

- | | | |
|----|-------------------------------------|-------------------|
| 47 | <u>X</u> PRESERVATION/STABILIZATION | NATIONAL |
| 48 | --- RESTORATION | <u>X</u> REGIONAL |
| 49 | --- RECONSTRUCTION | --- LOCAL |
| 50 | --- ADAPTIVE REUSE | |

51 ESTIMATED TREATMENT COSTS ---
52 ESTIMATED PLANNING/RESEARCH COSTS ---

Handwritten signature: J. N. K. E.

REF:

DATE OF CONTRIBUTION

LYNCH, OLIVE J.

1979. A PRELIMINARY INVENTORY OF CULTURAL RESOURCES OF
THE HOITHROD TRAIL BETWEEN RAINY PASS AND UNACUKLET.
BUREAU OF LAND MANAGEMENT, 1979

PETERSON, STEVEN, JR

1980 SITE SURVEY AND RECORDATION

~~UNACUKLET, B.C.~~

MISC: