	019	•	
	Mca 😅		
SITE Rohn River Checkpoint Cabin	AHRS NO: MeG-007	INHT NO: 220D	L
OTHER SITE NAMES:	TRAIL SECTION:		
Rohn River Roadhouse	Seward-Rainy Pass		
U.S. F&G Cabin	Rainy Pass-Kaltag	X	
FAA Cabin	Kaltag-Nome		T
Titana River CCC Cabin	_		
LAND STATUS: 3/6/8/ pm	· · · · · ·		_
D-1 State Selection F 15380	000	•	
Air Navigational Site Withdrawa	1-131		
PL05186	-		
· · · · · · · · · · · · · · · · · · ·		•	•
MTP 8-11-76			
LEGAL DESCRIPTION:			_
Approximate Actual X Quad. McGrath B-1			} } }
Marana 1 1			•
			•
Section 33			1
Subsection SW SW SE			Ī
		,	-
Latitude: 62 17' 45"			
Longitude: 153 23' 00"			
HTM DEEEDENCE.		•	ī
UTM REFERENCE:			•
Zone Easting	Northing		1
LOCATION AND USE:			
Control of the Contro	A. Carlotte and the control of the c		1
THERROTTE BY B (00)	DAME.	7	
INSPECTED BY: Peterson (80)	DATE: Aerial _	X Onsite	
STRUCTURAL TYPE: Shelter Stru	icture X River Com	munity	
	ing Community Other		
antendidorenado			
WALLS: IN OUT FLOOF	ROOF	CORNER NOTCH	4
Log-Rough X Dir	t Sod	X Unknown	•
Log-Hewn Woo		X Double Saddle	- 1
Frame Oth			
	X wd. Shingle	· · ·	_
Wall Covering	Tar Paper	· ·	
Unknown	Unknown	· ·	
TREATMENT RECOMMENDED:	ORDER OF SIGNIFICAN	JCF•	
TAMELITERY RECOURSEDED;	ORDER OF SIGNIFICAL	101.	
Site Protection	National	·	
X Preservation/Stabilization			
Restoration	Local		
Reconstruction			
Adaptive Reuse			
Estimated Treatment Costs	n diameters of the state of the		
Estimated Planning/Research Co	sts		

SITE Rohn River Checkpoint Cabin	AHRS	NO:	McG-007-	INHT NO:	220D
MANAGEMENT RATING CRITERIA					
ACCESS 40 POINTS					•
5 Difficult					
(Dog Sled, Snow Mach., Heli.)					•
20 X Medium					
(1 Day Hike, Boat, Fixed-Wing)					
40High					
(Auto/Road, Short Hike)			•		
CONDITION 40 POINTS					
Not Located				•	
1No Remains					
3Ruin				i de la companya de	
8Poor (Roof In)		-			
15 X Medium (Roof Intact)			7 H 1		
25 Good (Maintained)					
40 Restored					
PRESENT VISITOR USE					
Frequent					
X Infrequent				,	
None					
POTENTIAL VISITOR USE20 POINTS					
20 x High				-	
10 Medium					
5 Low					
Section 1					
Total Points 55		,			

STATEMENT OF SIGNIFICANCE:

Constructed by the Civilian Conservation Corps during the depression. The structure sits adjoining the Rohn River airstrip. May have been built in support of the airstrip construction as a survival cabin and/or as a weather station.

McPhrason 1914 shows RR CAMPHAT same Lacation

REFERENCE:

Lynch, Alice J., 1979. A Preliminary Inventory of Cultural Resources of the Iditarod Trail Between Rainy Pass and Unalakleet. Bureau of Land Management.

SITE RECOMMENDATIONS:

- 1. Maintain cabin for continued use in support of race activities and as a
- 2. Survival cabin: or a continued study of the
- 3. Include as part of the site modination to the
- 4. Stallingelan: and wood preservetives an
- 5. IN/OUT PLACE DUE TO AIRSTRIP.