

~~022~~

SITE NIKOLAI AHRS NO: MED-995 INHT NO: _____

OTHER SITE NAMES: _____ TRAIL SECTION:
Seward-Rainy Pass _____
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: ADP 3/19/81 per
VILLAGE SEL

LEGAL DESCRIPTION:
Approximate _____ Actual _____
Quad. Medfra A-3
Township T.28S, 29S
Range R. 23E, 24E
Section _____
Subsection _____

Latitude: _____
Longitude: _____

UTM REFERENCE:
A _____
Zone _____ Easting _____ Northing _____
LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement X Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 No Remains
- 3 Ruin
- 8 Poor (Roof In)
- 15 Medium (Roof Intact)
- 25 Good (Maintained)
- 40 Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
- 10 Medium
- 5 Low

Total Points 55

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS:

BILL SHYPER, N.P.S., PENALI STUDY, 1980