

SITE LOUDER AHRS NO: NUL-008 INHT NO: _____

OTHER SITE NAMES: _____ TRAIL SECTION:
Seward-Rainy Pass _____
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: ADP 3/19/81 pm
DI wild; VIL W/D; VIL SEL;
NATIVE ALLOT
FFD R/W

LEGAL DESCRIPTION:
Approximate _____ Actual _____
Quad. NUL C-2
Township 10S
Range 11E
Section 9
Subsection _____
Latitude: _____
Longitude: _____

UTM REFERENCE:
A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE: _____

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
20 Medium
(1 Day Hike, Boat, Fixed-Wing)
40 ___ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 No Remains
3 ___ Ruin
8 ___ Poor (Roof In)
15 ___ Medium (Roof Intact)
25 ___ Good (Maintained)
40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
 Infrequent
___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
10 ___ Medium
5 Low

Total Points 26

STATEMENT OF SIGNIFICANCE:

"Founded" by Ed. Mollner's father. -- site of a large maintained native settlement.

REFERENCE:

Pen. Comm - ED MOLLNER, GLENDA

SITE RECOMMENDATIONS: