

SITE CALIFORNIA ROADHOUSE

AHRS NO: _____

INHT NO: _____

OTHER SITE NAMES:

A.R.C. BELIEF CABIN ~ 1924

TRAIL SECTION:

Seward-Rainy Pass _____
Rainy Pass-Kaltag X
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate X Actual _____
Quad. OPH D-1
Township T185
Range R15E
Section
Subsection

Latitude: 63° 53' 00"
Longitude: 156° 00' 30"

UTM REFERENCE:

A _____
Zone Easting Northing

LOCATION AND USE:

UNKNOWN

INSPECTED BY: _____

DATE: _____

Aerial _____ Onsite _____

STRUCTURAL TYPE:

Shelter Structure X River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown <u> X </u>
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown <u> X </u>	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	<u> X </u>	<u> X </u>		Unknown <u> X </u>	

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- X LOGS
- _____ Site Protection _____ National
- _____ Preservation/Stabilization _____ Regional
- _____ Restoration _____ Local
- _____ Reconstruction
- _____ Adaptive Reuse

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 No Remains
- 3 Ruin
- 8 Poor (Roof In)
- 15 Medium (Roof Intact)
- 25 Good (Maintained)
- 40 Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
- 10 Medium
- 5 Low

Total Points 10

STATEMENT OF SIGNIFICANCE:

ROADHOUSE ON THE GRIPPLE LANDING TO POORMAN WINTER TRAIL.

An A.R.C Relief Cabin was constructed in this same vicinity in 1924

REFERENCE:

PURBY RECORD CITIZEN 1914
A.R.C Annual Report, 1924

SITE RECOMMENDATIONS: