

IDITAROD TRAIL INVENTORY

LEGAL DESCRIPTION:

Approximate Actual
 Quad. 041 D-1
 Township T18S
 Range R13E
 Section 20
 Subsection -

Latitude: 63° 55' -
 Longitude: 156° 21' -

UTM REFERENCE:

A
 Zone Easting Northing

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial Onsite

STRUCTURAL TYPE: Shelter Structure River Community
 Native Settlement Mining Community Other

<u>WALLS:</u>	<u>IN</u>	<u>OUT</u>	<u>FLOOR</u>	<u>ROOF</u>	<u>CORNER NOTCH</u>
Log-Rough	<input type="checkbox"/>	<input type="checkbox"/>	Dirt <input type="checkbox"/>	Sod <input type="checkbox"/>	Unknown <input checked="" type="checkbox"/>
Log-Hewn	<input type="checkbox"/>	<input type="checkbox"/>	Wood <input type="checkbox"/>	Metal <input type="checkbox"/>	
Frame	<input type="checkbox"/>	<input type="checkbox"/>	Other <input type="checkbox"/>	Wd. Plank <input type="checkbox"/>	
Drop Siding	<input type="checkbox"/>	<input type="checkbox"/>	Unknown <input checked="" type="checkbox"/>	Wd. Shingle <input type="checkbox"/>	
Wall Covering	<input type="checkbox"/>	<input type="checkbox"/>		Tar Paper <input type="checkbox"/>	
Unknown	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		Unknown <input checked="" type="checkbox"/>	

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- | | |
|---|-----------------------------------|
| <input type="checkbox"/> Site Protection | <input type="checkbox"/> National |
| <input type="checkbox"/> Preservation/Stabilization | <input type="checkbox"/> Regional |
| <input type="checkbox"/> Restoration | <input type="checkbox"/> Local |
| <input type="checkbox"/> Reconstruction | |
| <input type="checkbox"/> Adaptive Reuse | |

Estimated Treatment Costs _____
 Estimated Planning/Research Costs _____

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 No Remains
- 3 Ruin
- 8 Poor (Roof In)
- 15 Medium (Roof Intact)
- 25 Good (Maintained)
- 40 Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
- 10 Medium
- 5 Low

Total Points 10

STATEMENT OF SIGNIFICANCE:

UNKNOWN -- POSS NAME FOR ONE OF PAVE LEWIS'S EARLIER BODDHOUSES.

REFERENCE:

CHARLIE CARLOS, RUBY, AK, JULY 1980

SITE RECOMMENDATIONS:

LOCATE.