

SITE 1912 MINING CAMP AHRS NO: RUB 994 INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:
Seward-Rainy Pass _____
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: ADP 4/8/81
cl, st gnt

SEE RUB-001
FOR ADP PRINTOUT

LEGAL DESCRIPTION:

Approximate _____ Actual _____
Quad. RUB 994
Township 18S
Range 16E
Section 26
Subsection SE 501

Latitude: _____
Longitude: _____

UTM REFERENCE:

A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
20 Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 No Remains
3 Ruin
8 Poor (Roof In)
15 Medium (Roof Intact)
25 Good (Maintained)
40 Restored

PRESENT VISITOR USE

- Frequent
 Infrequent
 None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
10 Medium
5 Low

Total Points 25

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS: