| SITE NEW YORK CR PH. | AHRS NO: | INHT NO: |
|---|---|---|
| OTHER SITE NAMES: | TRAIL SECTION: Seward-Rainy Pass Rainy Pass-Kaltag Kaltag-Nome | |
| LAND STATUS: | | OH |
| | | |
| LEGAL DESCRIPTION: Approximate X Actual Quad. \underline{Pyg} Township $\underline{T105}$ Range \underline{E} $\underline{7E}$ Section $\underline{34}$ Subsection $(?)$ Latitude: $(4^{\circ} 35' (?)'')$ Longitude: $\underline{155^{\circ} 24'} (?)''$ UTM REFERENCE: \overline{A} | | AILIV |
| Zone Easting LOCATION AND USE: GENERAL NEED OF 14 Mi C INSPECTED BY: | DATE: Aerial | Onsite |
| | Ing Community Othe | er |
| Drop Siding Un Wall Covering Unknown <u>x x</u> | rt Sod od Metal her Wd. Plank known <u>x</u> Wd. Shingle Tar Paper Unknown | <u>CORNER NOTCH</u> Unknown <u>×</u> <u>X</u> |
| TREATMENT RECOMMENDED: _X Locate _X Site Protection Preservation/Stabilization Restoration Reconstruction Adaptive Reuse Estimated Treatment Costs | Local | x NCE: A |
| Estimated Planning/Research Co | osts | |

, 2, SITE

MANAGEMENT RATING CRITERIA ACCESS ----- 40 POINTS Difficult 5 (Dog Sled, Snow Mach., Heli.) 20 Medium (1 Day Hike, Boat, Fixed-Wing) 40× High (Auto/Road, Short Hike) CONDITION ---- 40 POINTS X Not Located 1 × No Remains 3 Ruin 8 Poor (Roof In) 15 Medium (Roof Intact) 25 Good (Maintained) 40 Restored PRESENT VISITOR USE Frequent x Infrequent None POTENTIAL VISITOR USE--20 POINTS 20 High 10 K Medium 5 Low

Total Points 51.

STATEMENT OF SIGNIFICANCE:

the New yor's creek Roadhan was constructed in 1911 duing the Gold Ruch activities in the fits the Roly ming District Records indicate that the structure was short lied and was probably put out of lusine in 1913 by the construction of the Halfevery Roadhane (14mis) in the serve rivering. the N.Y. Roadhane is significant because of its clarly association with the scritcal ming certicities in the District.

REFERENCE:

Rul Record Res Citizen, 1911,

SITE RECOMMENDATIONS: