

SITE A.P.L. WAREHOUSE AHRS NO: \_\_\_\_\_ INHT NO: \_\_\_\_\_

OTHER SITE NAMES: \_\_\_\_\_

TRAIL SECTION:

Seward-Rainy Pass \_\_\_\_\_  
Rainy Pass-Kaltag X  
Kaltag-Nome \_\_\_\_\_

LAND STATUS: \_\_\_\_\_

LEGAL DESCRIPTION:

Approximate X Actual \_\_\_\_\_  
Quad. RUB  
Township T11S  
Range R17E  
Section 20 OR 29  
Subsection ?

Latitude: 60° - 31' (?)  
Longitude: 155° - 31' (?)

UTM REFERENCE:

A \_\_\_\_\_  
Zone Easting Northing

LOCATION AND USE:

APPROX. 19 MILES FROM RUB 4.

INSPECTED BY: \_\_\_\_\_

DATE: \_\_\_\_\_

Aerial \_\_\_\_\_ Onsite \_\_\_\_\_

STRUCTURAL TYPE:

Shelter Structure \_\_\_\_\_ River Community \_\_\_\_\_  
Native Settlement \_\_\_\_\_ Mining Community \_\_\_\_\_ Other WAREHOUSE

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown <u>y</u>
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown <u>x</u>	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	<u>x</u>	<u>x</u>		Unknown	<u>x</u>

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- X LOCATE
- \_\_\_\_\_ Site Protection
- \_\_\_\_\_ Preservation/Stabilization
- \_\_\_\_\_ Restoration
- \_\_\_\_\_ Reconstruction
- \_\_\_\_\_ Adaptive Reuse

- \_\_\_\_\_ National
- \_\_\_\_\_ Regional
- X Local

Estimated Treatment Costs \_\_\_\_\_

Estimated Planning/Research Costs \_\_\_\_\_

IDITAROD TRAIL INVENTORY

SITE \_\_\_\_\_ AHRS NO: \_\_\_\_\_ INHT NO: \_\_\_\_\_

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 \_\_\_ Difficult  
(Dog Sled, Snow Mach., Heli.)
- 20 \_\_\_ Medium  
(1 Day Hike, Boat, Fixed-Wing)
- 40  High  
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 \_\_\_ No Remains
- 3 \_\_\_ Ruin
- 8 \_\_\_ Poor (Roof In)
- 15 \_\_\_ Medium (Roof Intact)
- 25 \_\_\_ Good (Maintained)
- 40 \_\_\_ Restored

PRESENT VISITOR USE

- \_\_\_ Frequent
- Infrequent
- \_\_\_ None

POTENTIAL VISITOR USE--20 POINTS

- 20 \_\_\_ High
- 10 \_\_\_ Medium
- 5  Low

Total Points 45

STATEMENT OF SIGNIFICANCE:

The Alaska Road Commission constructed a 16' x 40' x 10' warehouse at mile 19 in 1917. in support of trail/Road <sup>^</sup> activity in the area,   
maintained

Located approximately  
Just South of  
Hub Rd. House

REFERENCE:

A.E.C. Annual Report, 1916.

on Steve Peterson's (781  
Ruby <sup>Quarry</sup> <sub>1</sub> <sup>Map</sup>

SITE RECOMMENDATIONS:

LOCATE.