

IDITAROD TRAIL INVENTORY

Mile 53.1 Snowshed
 SITE Snowshed #2 AHRS NO: SEW-121 INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:
 Seward-Rainy Pass _____
 Rainy Pass-Kaltag _____
 Kaltag-Nome _____

LAND STATUS: ADP 4/7/81 pm
 R/W RR; REG SEL
 MULT USE

SEE SEW-121 FOR
 ADP PRINTOUT

LEGAL DESCRIPTION:

Approximate	Actual
Quad.	<u>SEW C-6</u>
Township	<u>7N</u>
Range	<u>2E</u>
Section	<u>23</u>
Subsection	<u>NE</u>
Latitude: <u>60° 41' 25"</u>	
Longitude: <u>149° 02' 35"</u>	

UTM REFERENCE:

A _____
 Zone Easting Northing

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
 Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- | | |
|----------------------------------|----------------|
| _____ Site Protection | _____ National |
| _____ Preservation/Stabilization | _____ Regional |
| _____ Restoration | _____ Local |
| _____ Reconstruction | |
| _____ Adaptive Reuse | |

Estimated Treatment Costs _____
 Estimated Planning/Research Costs _____

SITE Yonkers #2 AHRS NO: SCW-17 INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 No Remains
- 3 Ruin
- 8 Poor (Roof In)
- 15 Medium (Roof Intact)
- 25 Good (Maintained)
- 40 Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
- 10 Medium
- 5 Low

Total Points 13

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS:

USFS Signs (10/20)