

SITE Tunnel #1 AHRS NO: SEW-139 INHT NO: _____

OTHER SITE NAMES:

TRAIL SECTION:

Seward-Rainy Pass
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: ADP 4/7/01

SEE SEW-101 FOR
ADP PRINTOUT

R/W Federal - AKR
REG Sel
MULT USE

LEGAL DESCRIPTION:

Approximate _____ Actual _____
Quad. Seward Co
Township 7N
Range 2E
Section 35
Subsection SE

Latitude: 60 39 30
Longitude: 149 03 32

UTM REFERENCE:

A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE:

Abandoned Railroad Tunnel

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE Tunnel # 1 AHRS NO: SCW 129 INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 ___ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
- 1 ___ No Remains
- 3 ___ Ruin
- 8 ___ Poor (Roof In)
- 15 Medium (Roof Intact)
- 25 ___ Good (Maintained)
- 40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
- Infrequent
- ___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
- 10 ___ Medium
- 5 Low

Total Points 40

STATEMENT OF SIGNIFICANCE:

National Historic Site 11/28/77

REFERENCE:

SITE RECOMMENDATIONS:

VST 5 - Signage (10/80)