

## ALASKA ARCHAEOLOGICAL/HISTORICAL SURVEY RECORD CARD

SEW ~~436~~ 416

1. NAME OF SITE	2. PERTINENT DATES
Second Placer Creek Crossing Bridge	1925/1958
3. LOCATION Mile 47.2, ARR	
4. DESCRIPTION (DIMENSIONS, PRESENT CONDITION, SIGNIFICANT FEATURES, ETC.) On 2.2% compensated grade. 70# inner guard rail. Moved from old Loop M.P. 48.8 Two bents. Concrete abutments. 60-foot span. Steel stringers. Deck girder.	
5. SIGNIFICANCE Bridge fabricated during construction days of the Alaska Railroad. Originally in Loop District.	
6. DANGER OF DESTRUCTION	
7. RELEVANT PRINTED, MANUSCRIPT, PHOTOGRAPHIC REFERENCES ARR files, Anchorage	
8. OWNER OF PROPERTY/ADDRESS FED	9. DATE OF THIS REPORT 4.7.75 cmb

Space Below for ADP Use Only

C-6

QUAD ID SEW ID# ~~436~~ 416

RESOURCE NATURE H

DISTRICT \_\_\_\_\_ SITE \_\_\_\_\_

STRUCTURE  BUILDING \_\_\_\_\_

OBJECT \_\_\_\_\_

PLANNING REGION \_\_\_\_\_ THEME 5C

OWNERSHIP FED SIZE \_\_\_\_\_

LAT 60 39 25  
(DEG) (MIN) (SEC)

149 02 52  
(DEG) (MIN) (SEC)

PRESERVATION STATUS \_\_\_\_\_

NAME 2d Placer Cr. Crossing Bridge

1925/1958

DATES \_\_\_\_\_ RELIABILITY 1

Coded By: \_\_\_\_\_ Date: \_\_\_\_\_