

SITE Snoering Inn AHRS NO: _____ LNHT NO: _____

OTHER SITE NAMES: _____ TRAIL SECTION:
 Seward-Rainy Pass
 Rainy Pass-Kaltag _____
 Kaltag-Nome _____
 Kenai Peninsula Branch Trails _____

LAND STATUS: ADP 4/2/81
 CHANGING FROM...
 R/W R/R, REG 5441
 MULT USE

LEGAL DESCRIPTION:
 Approximate Actual _____
 Quad. 51N (C6)
 Township 6N
 Range 2E
 Section 22
 Subsection SW 1/4
 Latitude: 61° 03' 35" N
 Longitude: 149° 03' 35" W

UTM REFERENCE:
 A 06 385870 6119515
 Zone Easting Northing

LOCATION AND USE:
 LOCATION: ... DATE: 8/81

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
 Native Settlement _____ Mining Community _____ Other Inn

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown <input checked="" type="checkbox"/>
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	<input checked="" type="checkbox"/>	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown <input checked="" type="checkbox"/>	Wd. Shingle	_____
Wall Covering	<input checked="" type="checkbox"/>	_____		Tar Paper	<input checked="" type="checkbox"/>
Unknown	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		Unknown	<input checked="" type="checkbox"/>
				BOARD & BAT. WOOD	

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ Archeological Investigation
- _____ National
- _____ Regional
- Local

Estimated Treatment Costs _____
 Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE CHOCUNG HILL

AHRS NO: _____

INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 No Remains
- 3 Ruin
- 8 Poor (Roof In)
- 15 Medium (Roof Intact)
- 25 Good (Maintained)
- 40 Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
- 10 Medium
- 5 Low

Total Points 13

STATEMENT OF SIGNIFICANCE:

Structure, possibly one of the buildings at the site, is a good example of a building of this type. It is a simple, rectangular building with a gabled roof. The building is made of wood and is in good condition. It is a good example of a building of this type. The building is a good example of a building of this type.

Ed Estes claims that the structure was owned by an individual called "Blackie" who used the structure to trap and prospect for gold. Blackie also had a cabin in Moose Pass called the "Snowy Out". (Refer to logs/transcript). To his knowledge, it was never used as a roadhouse or Railroad Way Station.

REFERENCE:

*used as a roadhouse (reference)
AEC MAP, DEC 1914, BRECK (SURVEY ENGINEER)*

PEDS COMM) EP, ESTES, MOOSE PASS, JUNE 1981 -> OWNER "BLACKIE"

SITE RECOMMENDATIONS:

Collect artifacts from the site and accession as a collection