SITE TRAPPERS CABIN	AHRS NO:	INHT NO:	K
OTHER SITE NAMES:	TRAIL SECTION: Seward-Rainy Pass Rainy Pass-Kaltag Kaltag-Nome	and the second se	ORY
LAND STATUS:		an a	ENT
			<u> </u>
LEGAL DESCRIPTION:			FJ
Approximate Actual X Quad. <u>ZEW</u> Township Range Section Subsection	REFER PETHECON	1981 MAP	INV
Latitude: Longitude:			
	Northing		AIL
LOCATION AND USE: EAST SIDE OF P.P. ± 1/2 INSPECTED BY: PEITESON	DATE: JINES Aerial _	¥ 1	E E
EAST SIDE OF P.P. ± 1/2 INSPECTED BY: PEIESON STRUCTURAL TYPE: Shelter Stru	DATE: JINEG Aerial	V Onsite	-
EAST SIDE OF P.P. ± 1/2 INSPECTED BY: PEIESON STRUCTURAL TYPE: Shelter Stru	DATE: JINEG Aerial	X Onsite	-
EAST SIDE OF P.P., ± 1/2 <u>INSPECTED BY:</u> PEITESON <u>STRUCTURAL TYPE:</u> Shelter Stru Native Settlement Mint <u>WALLS: IN OUT FLOOF</u> Log-RoughX Din Log-Hewn Woo Frame Oth	DATE: JINEG Aerial acture River Com Ing Community Oth R ROOF rt Sod od Metal	X Onsite munity	-
EAST SIDE OF P.P. ± 1/2 INSPECTED BY: PEITESON STRUCTURAL TYPE: Shelter Strument Mative Settlement Ministrative Settlement MALLS: IN OUT FLOOF Log-Rough X Din Log-Hewn Oth Drop Siding Wall Covering	DATE: INEG Aerial neture River Com Ing Community Oth R ROOF rt Sod od Metal her Wd. Plank known X Wd. Shingle Tar Paper	V Onsite munity	-
EAST SIDE OF P.P., ± 1/2 INSPECTED BY: PEIDSON STRUCTURAL TYPE: Shelter Strument Native Settlement Minite WALLS: IN Log-Rough X Log-Hewn Wood Frame Oth Drop Siding Unite Wall Covering Unite Unknown X TREATMENT RECOMMENDED: X Site Protection X Preservation/Stabilization Restoration Adaptive Reuse Adaptive Reuse	DATE: VINE & Aerial incture River Community Oth R ROOF rt Sod rt Sod rt Sod Metal her Wd. Plank known X Wd. Shingle Tar Paper Unknown ORDER OF SIGNIFICA National	X Onsite munity	-
EAST SIDE OF P.P., ± 1/2 INSPECTED BY: PEIDESON STRUCTURAL TYPE: Shelter Stru Native Settlement Mind WALLS: IN OUT Log-Rough X Din Log-Rough X Din Log-Rough X Din Log-Hewn Wood Frame Ott Drop Siding Univ Wall Covering Univ Unknown X TREATMENT RECOMMENDED: X Site Protection X Restoration Restoration	DATE: VINE & Aerial	X Onsite munity	-
EAST SIDE OF P.P., ± 1/2 INSPECTED BY: PEIDESON STRUCTURAL TYPE: Shelter Strument Native Settlement Minite WALLS: IN Log-Rough X Log-Rough X Distructural type: Minite WALLS: IN OUT FLOOF Log-Rough X Distructural type: Wood Frame Other Drop Siding Unite Wall Covering Unite Unknown X TREATMENT RECOMMENDED:	DATE: VINE & Aerial	X Onsite munity	-

SITE

1.20

P®

MANAGEMENT RATING CRITERIA		
ACCESS 40 POINTS		
5Difficult		
(Dog Sled, Snow Mach., Heli.)		
20× Medium		
(1 Day Hike, Boat, Fixed-Wing)		
40 High		
(Auto/Road, Short Hike)		
CONDITION 40 POINTS		
Not Located		
1 No Remains		
3 Ruin		
8 Poor (Roof In)		
15 🗙 Medium (Roof Intact)		
25 Good (Maintained)		
40 Restored		
PRESENT VISITOR USE		
Frequent		
X Infrequent		
None		
POTENTIAL VISITOR USE20 POINTS		
20 × High		
10 Medium		
5 Low		
Total Points <u>55</u>		

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS: