

SITE YALCRAHAROD TRAIL AHRS NO: SEW-035 INHT NO: 1891

OTHER SITE NAMES:

TRAIL SECTION:

- Seward-Rainy Pass
- Rainy Pass-Kaltag
- Kaltag-Nome
- Kenai Peninsula Branch Trails

LAND STATUS: ADP 4/7/81  
NATIONAL FOREST; WYD Ap/Inj  
REG SEL; PLACER CLMS;  
UNKNOWN

SEE SEW-035 FOR  
ADP PRINTOUT

LEGAL DESCRIPTION:

Approximate Quad.	<u>SEW C7</u>	Actual <input checked="" type="checkbox"/>
Township	<u>7N</u>	
Range	<u>1W</u>	
Section	<u>28</u>	
Subsection	<u>SW SW</u>	

Latitude: 60° 57' 20" N  
Longitude: 149° 28' 35" W

UTM REFERENCE:

<u>A</u>	<u>0</u>	<u>6</u>	<u>3</u>	<u>6</u>	<u>4</u>	<u>9</u>	<u>7</u>	<u>5</u>	<u>6</u>	<u>7</u>	<u>2</u>	<u>7</u>	<u>4</u>	<u>4</u>	<u>0</u>
Zone			Easting					Northing							

LOCATION AND USE: Overgrown Forest

INSPECTED BY: \_\_\_\_\_ DATE: \_\_\_\_\_ Aerial  Onsite

STRUCTURAL TYPE: Shelter Structure  River Community   
 Native Settlement  Mining Community  Other Overgrown

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	<input type="checkbox"/>	<input type="checkbox"/>	Dirt <input type="checkbox"/>	Sod <input type="checkbox"/>	Unknown <input type="checkbox"/>
Log-Hewn	<input type="checkbox"/>	<input type="checkbox"/>	Wood <input type="checkbox"/>	Metal <input type="checkbox"/>	
Frame	<input type="checkbox"/>	<input type="checkbox"/>	Other <input type="checkbox"/>	Wd. Plank <input type="checkbox"/>	
Drop Siding	<input type="checkbox"/>	<input type="checkbox"/>	Unknown <input type="checkbox"/>	Wd. Shingle <input type="checkbox"/>	
Wall Covering	<input type="checkbox"/>	<input type="checkbox"/>		Tar Paper <input type="checkbox"/>	
Unknown	<input type="checkbox"/>	<input type="checkbox"/>		Unknown <input type="checkbox"/>	

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- |  |   |
|--|---|
| <input checked="" type="checkbox"/> Site Protection  | <input type="checkbox"/> National         |
| <input type="checkbox"/> Preservation/Stabilization  | <input type="checkbox"/> Regional         |
| <input type="checkbox"/> Restoration                 | <input checked="" type="checkbox"/> Local |
| <input type="checkbox"/> Reconstruction              |   |
| <input type="checkbox"/> Adaptive Reuse              |   |
| <input type="checkbox"/> Archeological Investigation |   |
| Estimated Treatment Costs _____                      |   |
| Estimated Planning/Research Costs _____              |   |

YALCRAHAROD TRAIL INVENTORY

SITE CRICKET COURT

AHRS NO: STATION

INHT NO: 1001

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5  Difficult  
(Dog Sled, Snow Mach., Heli.)
- 20  Medium  
(1 Day Hike, Boat, Fixed-Wing)
- 40  High  
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1  No Remains
- 3  Ruin
- 8  Poor (Roof In)
- 15  Medium (Roof Intact)
- 25  Good (Maintained)
- 40  Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20  High
- 10  Medium
- 5  Low

Total Points 53

STATEMENT OF SIGNIFICANCE:

The site is a small, rectangular, single-story building with a gabled roof. It is located on a hillside overlooking the town of... The building is in poor condition, with significant structural damage and a partially collapsed roof. The site is surrounded by dense forest and is accessible only by a narrow trail. The building is believed to be a remnant of a military installation from the early 20th century. The site is of historical significance due to its association with the military and its location in a remote area. The building is a good example of early 20th-century military architecture and is a valuable resource for the study of military history. The site is also of interest to the local community as a reminder of the military presence in the area.

REFERENCE:

Historical Map of the Area of the Site

SITE RECOMMENDATIONS: