

SITE INDIAN R.H. SITE

AHRS NO: _____

INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass
Rainy Pass-Kaltag X
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate X Actual _____
Quad. SEIN D-7
Township TION
Range RIW
Section 6
Subsection _____

Latitude: _____

Longitude: _____

UTM REFERENCE:

A _____
Zone Easting Northing

LOCATION AND USE:

MILEPOST 103, SEWARD HIGHWAY, WEST SIDE OF INDIAN CR.

INSPECTED BY: _____

DATE: _____

Aerial _____ Onsite _____

STRUCTURAL TYPE:

Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

_____ Site Protection
_____ Preservation/Stabilization
_____ Restoration
_____ Reconstruction
_____ Adaptive Reuse

_____ National
_____ Regional
_____ Local

Estimated Treatment Costs _____

Estimated Planning/Research Costs _____

INDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
- 1 ___ No Remains
- 3 Ruin
- 8 ___ Poor (Roof In)
- 15 Medium (Roof Intact)
- 25 ___ Good (Maintained)
- 40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
- Infrequent
- ___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
- 10 Medium
- 5 ___ Low

Total Points 60

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS:

LOCATE & RECORP, what is remaining structure? Interpret