

SITE THE BIRD HOUSE AHRS NO: _____ INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass X
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate _____ Actual _____
Quad. ANL.
Township _____
Range _____
Section _____
Subsection _____

Latitude: _____
Longitude: _____

UTM REFERENCE:

A _____
Zone Easting Northing

LOCATION AND USE: _____

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- | | |
|----------------------------------|----------------|
| _____ Site Protection | _____ National |
| _____ Preservation/Stabilization | _____ Regional |
| _____ Restoration | _____ Local |
| _____ Reconstruction | |
| _____ Adaptive Reuse | |

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDENTIFIED TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
1 ___ No Remains
3 ___ Ruin
8 ___ Poor (Roof In)
15 ___ Medium (Roof Intact)
25 Good (Maintained)
40 ___ Restored

PRESENT VISITOR USE

- Frequent
___ Infrequent
___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
10 ___ Medium
5 ___ Low

Total Points 85

STATEMENT OF SIGNIFICANCE:

Serves as a bar at present time,

REFERENCE:

SITE RECOMMENDATIONS: