

SITE White's Roadhouse AHRS NO: SEW-105 INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:
Seward-Rainy Pass
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: ADP 4/7/81
NATIONAL FOREST; FED OWN WYO;
MULT USE; REG SEL;
PLAVER CUM

LEGAL DESCRIPTION:

Approximate Quad. SEW C7 Actual _____
Township 7N
Range 1E
Section 9 ^{or 4}
Subsection NW NE ^{SW}
Latitude: 60° 43'
Longitude: 149° 17'

UTM REFERENCE:

A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE White's Roundhouse AHRS NO: SEW-105 INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 No Remains
- 3 Ruin
- 8 Poor (Roof In)
- 15 Medium (Roof Intact)
- 25 Good (Maintained)
- 40 Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20 High
- 10 Medium
- 5 Low

Total Points _____

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS:

USFS - National Register Nominations
Restoration
Interpretation (10/90)
Ad-Plus, etc

SITE SEWARD RAINY PASS AHRS NO: 521103 INHT NO: 521103

OTHER SITE NAMES:

TRAIL SECTION:

Seward-Rainy Pass
 Rainy Pass-Kaltag
 Kaltag-Nome
 Kenai Peninsula Branch Trails

LAND STATUS:

SEE SEW-000
 "GLEASON'S CABIN"
 FOR ADP PRINTOUT

LEGAL DESCRIPTION:

Approximate Actual
 Quad. SECOF
 Township T 7N
 Range R 1E
 Section 9
 Subsection ?

CAMP 5/81

Latitude: 60° 47' 42" N } 60° 42' 40"
 Longitude: 149° 11' 30" W } 149° 20' 40"

UTM REFERENCE:

A 16 375075 6732550
 Zone Easting Northing

LOCATION AND USE: On road, near site of Gleason's Cabin, 2 miles north of Seward
7/12/91 (10/12/91 in ADP)

INSPECTED BY: _____ DATE: _____ Aerial Onsite

STRUCTURAL TYPE: Shelter Structure River Community
 Native Settlement Mining Community Other ROADHOUSE

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	<input type="checkbox"/>	<input type="checkbox"/>	Dirt <input type="checkbox"/>	Sod <input type="checkbox"/>	Unknown <input type="checkbox"/>
Log-Hewn	<input type="checkbox"/>	<input type="checkbox"/>	Wood <input type="checkbox"/>	Metal <input type="checkbox"/>	
Frame	<input type="checkbox"/>	<input type="checkbox"/>	Other <input type="checkbox"/>	Wd. Plank <input type="checkbox"/>	
Drop Siding	<input type="checkbox"/>	<input type="checkbox"/>	Unknown <input type="checkbox"/>	Wd. Shingle <input type="checkbox"/>	
Wall Covering	<input type="checkbox"/>	<input type="checkbox"/>		Tar Paper <input type="checkbox"/>	
Unknown	<input checked="" type="checkbox"/>	<input type="checkbox"/>		Unknown <input type="checkbox"/>	

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- Site Protection
- Preservation/Stabilization
- Restoration
- Reconstruction
- Adaptive Reuse
- Archeological Investigation
- Estimated Treatment Costs _____
- Estimated Planning/Research Costs _____
- National
- Regional
- Local

IDITAROD TRAIL INVENTORY

