

SITE Indian Summit Site AHRS NO: SEW-125 INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: ADP 4/7/81 am
CLASSIF: FED PWR W/D; PL0 1613?
HOMESITE; R/W PWR;
ST GNT; REG SEL; PLACER CLM

SEE SEW-125
FOR ADP PRINTOUT

LEGAL DESCRIPTION:

Approximate _____ Actual _____
Quad. SE W D.1
Township 10N
Range 1W
Section 5
Subsection SE SW NW

Latitude: 60° 59' 15"
Longitude: 149° 30' 00"

UTM REFERENCE:

A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE: _____

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt _____	Sod _____	Unknown _____
Log-Hewn	_____	_____	Wood _____	Metal _____	
Frame	_____	_____	Other _____	Wd. Plank _____	
Drop Siding	_____	_____	Unknown _____	Wd. Shingle _____	
Wall Covering	_____	_____		Tar Paper _____	
Unknown	_____	_____		Unknown _____	

TREATMENT RECOMMENDED: _____

ORDER OF SIGNIFICANCE: _____

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

INDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
- 1 No Remains
- 3 ___ Ruin
- 8 ___ Poor (Roof In)
- 15 ___ Medium (Roof Intact)
- 25 ___ Good (Maintained)
- 40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
- Infrequent
- ___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
- 10 ___ Medium
- 5 Low

Total Points 46

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS: