

SITE Bruhn-Ray Mine AHRS NO: SCW-197 INHT NO: \_\_\_\_\_

OTHER SITE NAMES: \_\_\_\_\_ TRAIL SECTION:  
Seward-Rainy Pass X  
Rainy Pass-Kaltag      
Kaltag-Nome    

LAND STATUS: \_\_\_\_\_  
Federal-USFS - Active Mining Claim

LEGAL DESCRIPTION:  
Approximate \_\_\_\_\_ Actual \_\_\_\_\_  
Quad. 5E4 D7  
Township 8N  
Range 1W  
Section 15  
Subsection NW SW SE  
  
Latitude: 60° 46' 48"  
Longitude: 149° 25' 40"

UTM REFERENCE:  
A \_\_\_\_\_  
Zone \_\_\_\_\_ Easting \_\_\_\_\_ Northing \_\_\_\_\_

LOCATION AND USE: \_\_\_\_\_

INSPECTED BY: \_\_\_\_\_ DATE: \_\_\_\_\_ Aerial \_\_\_\_\_ Onsite \_\_\_\_\_

STRUCTURAL TYPE: Shelter Structure \_\_\_\_\_ River Community \_\_\_\_\_  
Native Settlement \_\_\_\_\_ Mining Community \_\_\_\_\_ Other \_\_\_\_\_

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	___	___	Dirt	Sod	Unknown
Log-Hewn	___	___	Wood	Metal	___
Frame	___	___	Other	Wd. Plank	___
Drop Siding	___	___	Unknown	Wd. Shingle	___
Wall Covering	___	___		Tar Paper	___
Unknown	___	___		Unknown	___

TREATMENT RECOMMENDED: \_\_\_\_\_ ORDER OF SIGNIFICANCE: \_\_\_\_\_

- |                                |              |
|--------------------------------|--------------|
| ___ Site Protection            | ___ National |
| ___ Preservation/Stabilization | ___ Regional |
| ___ Restoration                | ___ Local    |
| ___ Reconstruction             |              |
| ___ Adaptive Reuse             |              |

Estimated Treatment Costs \_\_\_\_\_  
Estimated Planning/Research Costs \_\_\_\_\_

IDITAROD TRAIL INVENTORY

SITE Bruhn Ray Mine

AHRS NO: SCW-197

INHT NO: \_\_\_\_\_

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5  Difficult  
(Dog Sled, Snow Mach., Heli.)
- 20  Medium  
(1 Day Hike, Boat, Fixed-Wing)
- 40  High  
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1  No Remains
- 3  Ruin
- 8  Poor (Roof In)
- 15  Medium (Roof Intact)
- 25  Good (Maintained)
- 40  Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20  High
- 10  Medium
- 5  Low

Total Points \_\_\_\_\_

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS:

USFS - Restoration, Signing. Adaptive Use 10/80

SITE BROWN-PC 10-17 AHRS NO: FW 101 INHT NO: FS 212

OTHER SITE NAMES:

TRAIL SECTION:

Seward-Rainy Pass \_\_\_\_\_  
 Rainy Pass-Kaltag \_\_\_\_\_  
 Kaltag-Nome \_\_\_\_\_  
 Kenai Peninsula Branch Trails

LAND STATUS:

ADP 4/7/81 pm  
 NE; w/d Apn; Reg Sel;  
 SF GNT; PLACER CLM;  
 LODG CLM; TUNNEL SITE;  
 etc

LEGAL DESCRIPTION:

Approximate \_\_\_\_\_ Actual   
 Quad. 2N 1W 1E  
 Township 8N  
 Range 1W  
 Section 1E  
 Subsection NE 1/4

THIS ADP PRINT ALSO APPLIES  
 TO SEW-000  
 (WYBLE'S CABIN)

Latitude: 60°46'30" N  
 Longitude: 149°26'00" W

UTM REFERENCE:

A 06 368460 6740200  
 Zone Easting Northing

LOCATION AND USE: Mining camp on the river bank

INSPECTED BY: \_\_\_\_\_ DATE: \_\_\_\_\_ Aerial \_\_\_\_\_ Onsite \_\_\_\_\_

STRUCTURAL TYPE: Shelter Structure \_\_\_\_\_ River Community \_\_\_\_\_  
 Native Settlement \_\_\_\_\_ Mining Community  Other \_\_\_\_\_

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	<input checked="" type="checkbox"/>	Dirt _____	Sod _____	Unknown <input checked="" type="checkbox"/>
Log-Hewn	_____	_____	Wood _____	Metal _____	
Frame	_____	_____	Other _____	Wd. Plank _____	
Drop Siding	_____	_____	Unknown _____	Wd. Shingle _____	
Wall Covering	_____	_____		Tar Paper <input checked="" type="checkbox"/>	
Unknown	<input checked="" type="checkbox"/>	_____		Unknown _____	

TREATMENT RECOMMENDED: \_\_\_\_\_ ORDER OF SIGNIFICANCE: \_\_\_\_\_

Site Protection  
 Preservation/Stabilization  
 Restoration  
 Reconstruction  
 Adaptive Reuse  
 Archeological Investigation  
 Estimated Treatment Costs \_\_\_\_\_  
 Estimated Planning/Research Costs \_\_\_\_\_

National  
 Regional  
 Local

IDITAROD TRAIL INVENTORY

