

SITE SIBLEY'S TENT RH

AHRS NO: _____

INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass _____
 Rainy Pass-Kaltag X
 Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate _____ Actual _____
 Quad. _____
 Township _____
 Range _____
 Section _____
 Subsection _____
 Latitude: _____
 Longitude: _____

} UNKNOWN

UTM REFERENCE:

A _____
 Zone Easting Northing

LOCATION AND USE:

ANGHT. SIDE OF INDIAN PASS - ON TURNIGAN / JOHNSON
 TRAIL 1 97.30 MI FROM SEWARD

INSPECTED BY: _____

DATE: _____

Aerial _____ Onsite _____

STRUCTURAL TYPE:

Shelter Structure _____ River Community _____
 Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown <u>X</u>
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown <u>V</u>	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	<u>X</u>	<u>X</u>		Unknown	<u>V</u>

TREATMENT RECOMMENDED:

- X LOCATE
- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse

ORDER OF SIGNIFICANCE:

- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____

Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 ___ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1 No Remains
- 3 ___ Ruin
- 8 ___ Poor (Roof In)
- 15 ___ Medium (Roof Intact)
- 25 ___ Good (Maintained)
- 40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
- Infrequent
- ___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
- 10 ___ Medium
- 5 Low

Total Points 26

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS: