

SITE PUNTILLA CABIN

AHRS NO: ^{TAL-044} TAL-998

INHT NO: _____

OTHER SITE NAMES:
PONTELLA CABIN

TRAIL SECTION:
Seward-Rainy Pass _____
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:
Approximate _____ Actual _____
Quad. TAL R6
Township 23N
Range 19W
Section 24
Subsection NW NW

Latitude: 62° 11' 30"
Longitude: 152° 41' 00"

UTM REFERENCE:
A _____
Zone Easting Northing

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 ___ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
- 1 ___ No Remains
- 3 ___ Ruin
- 8 ___ Poor (Roof In)
- 15 ___ Medium (Roof Intact)
- 25 ___ Good (Maintained)
- 40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
- ___ Infrequent
- ___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
- 10 ___ Medium
- 5 ___ Low

Total Points _____

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS: