

045

SITE BEAR CREEK CABIN

AHRS NO: TYO-045 INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass X
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate _____ Actual X
Quad. TYO-C-3
Township T19N
Range R9W
Section 20
Subsection SW¹/₄, SW²/₄, NW¹/₄

Latitude: 61° 43' 05"
Longitude: 150° 57' 20"

UTM REFERENCE:

A _____
Zone _____ Easting _____ Northing _____

LOCATION AND USE: _____

INSPECTED BY: S. Peters

DATE: Jun 12, 81 Aerial X Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other UNKN.

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	<u>X</u>	Dirt	Sod	Unknown <u>X</u>
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	<u>X</u>	_____		Unknown	<u>X</u>

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- X Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
20 Medium
(1 Day Hike, Boat, Fixed-Wing)
40 ___ High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 ___ No Remains
3 ___ Ruin
8 Poor (Roof In)
15 ___ Medium (Roof Intact)
25 ___ Good (Maintained)
40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
 Infrequent
 None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
10 Medium
5 ___ Low

Total Points 38.

STATEMENT OF SIGNIFICANCE:

UNKNOWN -

REFERENCE:

-None -

SITE RECOMMENDATIONS:

RESEARCH - POTENTIAL AS A RESTORED/RECONST. CABIN