

SITE ROADHOUSE (Kaltag area) AHRS NO: TYO-048 INHT NO: /

OTHER SITE NAMES:

TRAIL SECTION:

Seward-Rainy Pass   
 Rainy Pass-Kaltag \_\_\_\_\_  
 Kaltag-Nome \_\_\_\_\_

LAND STATUS: \_\_\_\_\_

LEGAL DESCRIPTION:

Approximate  Actual  
 Quad. TYO D-3  
 Township T20N  
 Range R8W  
 Section 5  
 Subsection SW 1/4

Latitude: 61° 50' 45"  
 Longitude: 160° 45' 50"

UTM REFERENCE:

A \_\_\_\_\_  
 Zone Easting Northing

LOCATION AND USE:

SOUTH SIDE OF KAHILTNA RIVER, N. SIDE OF YENTNA RIVER

INSPECTED BY:

DATE:

Aerial \_\_\_\_\_ Onsite \_\_\_\_\_

STRUCTURAL TYPE:

Shelter Structure  River Community \_\_\_\_\_  
 Native Settlement \_\_\_\_\_ Mining Community \_\_\_\_\_ Other \_\_\_\_\_

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	___	___	Dirt	Sod	Unknown
Log-Hewn	___	___	Wood	Metal	___
Frame	___	___	Other	Wd. Plank	___
Drop Siding	___	___	Unknown	Wd. Shingle	___
Wall Covering	___	___		Tar Paper	___
Unknown	___	___		Unknown	___

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

- \_\_\_ Site Protection
- \_\_\_ Preservation/Stabilization
- \_\_\_ Restoration
- \_\_\_ Reconstruction
- \_\_\_ Adaptive Reuse

- \_\_\_ National
- \_\_\_ Regional
- \_\_\_ Local

Estimated Treatment Costs \_\_\_\_\_

Estimated Planning/Research Costs \_\_\_\_\_

# IDITAROD TRAIL INVENTORY

SITE \_\_\_\_\_ AHRS NO: \_\_\_\_\_ INHT NO: \_\_\_\_\_

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5  Difficult  
(Dog Sled, Snow Mach., Heli.)
- 20  Medium  
(1 Day Hike, Boat, Fixed-Wing)
- 40  High  
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1  No Remains
- 3  Ruin
- 8  Poor (Roof In)
- 15  Medium (Roof Intact)
- 25  Good (Maintained)
- 40  Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20  High
- 10  Medium
- 5  Low

Total Points 75

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SLEEM'S MAP OF CENTRAL ALASKA, 1910 → LOCATES A ROADHOUSE

SITE RECOMMENDATIONS: