

SITE Eaton's

AHRS NO: UKT-XXY ... NO: \_\_\_\_\_

OTHER SITE NAMES: \_\_\_\_\_

TRAIL SECTION:

Seward-Rainy Pass \_\_\_\_\_  
Rainy Pass-Kaltag \_\_\_\_\_  
Kaltag-Nome \_\_\_\_\_

LAND STATUS: \_\_\_\_\_

WHALE BACK CABIN (UKT-026)  
ALSO CALLED EATON'S

LEGAL DESCRIPTION:

Approximate	<input checked="" type="checkbox"/>	Actual
Quad.	<u>VNK-D4</u>	
Township	<u>19S</u>	<u>18S</u>
Range	<u>10W</u>	<u>8W</u>
Section	<u>11</u>	<u>30</u>
Subsection	<u>NE</u>	<u>NW</u>

Latitude: \_\_\_\_\_  
Longitude: \_\_\_\_\_

UTM REFERENCE:

A	Zone	Easting	Northing
	_____	_____	_____

LOCATION AND USE: \_\_\_\_\_

INSPECTED BY: \_\_\_\_\_

DATE: \_\_\_\_\_

Aerial \_\_\_\_\_

Onsite \_\_\_\_\_

STRUCTURAL TYPE:

Shelter	Structure	River Community
Native Settlement	Mining Community	Other
_____	_____	_____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

Site Protection  
 Preservation/Stabilization  
 Restoration  
 Reconstruction  
 Adaptive Reuse

National  
 Regional  
 Local

Estimated Treatment Costs \_\_\_\_\_  
 Estimated Planning/Research Costs \_\_\_\_\_

IDITAROD TRAIL INVENTORY

SITE Eaton's AHRS NO: \_\_\_\_\_ INHT NO: \_\_\_\_\_

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5  Difficult  
(Dog Sled, Snow Mach., Heli.)
- 20  Medium  
(1 Day Hike, Boat, Fixed-Wing)
- 40  High  
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
- 1  No Remains
- 3  Ruin
- 8  Poor (Roof In)
- 15  Medium (Roof Intact)
- 25  Good (Maintained)
- 40  Restored

PRESENT VISITOR USE

- Frequent
- Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20  High
- 10  Medium
- 5  Low

Total Points 31

STATEMENT OF SIGNIFICANCE:

Eaton's is nationally significant because of its association with the Iditarod National Historic Trail. Existing historic maps identify three possible locations for Eaton's cabin; the exact location is unknown. The Eaton cabin was constructed in support of reindeer herding activities in the area during the 1920s.

REFERENCE:

SITE RECOMMENDATIONS: