



Underwater contours from survey made by  
Anchorage Public Utilities, February, 1947  
Shore line as of May 19, 1947  
Lake surface 860.3

EKLUTNA LAKE DAMSITE



Topography by Arthur Johnson and L. T. Cook  
Horizontal Control in part by Anchorage Public Utilities  
Surveyed in 1947  
SURVEYED IN COOPERATION WITH ANCHORAGE PUBLIC UTILITIES



Subject to adjustment  
All crosses (X) and triangles (Δ) are plane  
table bench marks except those marked BM

3 plan sheets, 1 of which shows damsite