

SITE CABIN FOUNDATIONS AHRS NO: ANC-104 INHT NO: ANC-996

OTHER SITE NAMES: M.P. 109.2 CABIN
TERMINUS POINT OF A.G. NORTH. R.R.
VER 1 P 4

TRAIL SECTION:
Seward-Rainy Pass _____
Rainy Pass-Kaltag _____
Kaltag-Nome _____

LAND STATUS:
R/W RR; R/W PWR TR;
OPENING ORDER; ST GNT;
CLASSIF;
REG Sel

SEE ANC 999
FOR ADP PRINTOUT

LEGAL DESCRIPTION:

| Approximate | Actual |
|-------------|----------------|
| Quad. | <u>ANC A-2</u> |
| Township | <u>11N</u> |
| Range | <u>2W</u> |
| Section | <u>30</u> |
| Subsection | <u>SE SE</u> |

Latitude: _____
Longitude: _____

UTM REFERENCE:
A _____
Zone Easting Northing

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
Native Settlement _____ Mining Community _____ Other _____

| WALLS: | IN | OUT | FLOOR | ROOF | CORNER NOTCH |
|---------------|-------|-------|---------|-------------|--------------|
| Log-Rough | _____ | _____ | Dirt | Sod | Unknown |
| Log-Hewn | _____ | _____ | Wood | Metal | _____ |
| Frame | _____ | _____ | Other | Wd. Plank | _____ |
| Drop Siding | _____ | _____ | Unknown | Wd. Shingle | _____ |
| Wall Covering | _____ | _____ | | Tar Paper | _____ |
| Unknown | _____ | _____ | | Unknown | _____ |

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

| | |
|----------------------------------|----------------|
| _____ Site Protection | _____ National |
| _____ Preservation/Stabilization | _____ Regional |
| _____ Restoration | _____ Local |
| _____ Reconstruction | |
| _____ Adaptive Reuse | |

Estimated Treatment Costs _____
Estimated Planning/Research Costs _____

IDENTIFIED TRAIL INVENTORY

SITE _____ AHRS NO: AUC-104 INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
- 20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
- 40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
- 1 ___ No Remains
- 3 Ruin
- 8 ___ Poor (Roof In)
- 15 ___ Medium (Roof Intact)
- 25 ___ Good (Maintained)
- 40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
- ___ Infrequent
- None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
- 10 ___ Medium
- 5 Low

Total Points 40

STATEMENT OF SIGNIFICANCE:

REFERENCE:

NEC RR. MAP, DEC. 1916 → LOCATES THE END OF THEIR ROAD BED IN THIS AREA. — POSS
CABIN RUINS ARE AT THAT POINT.

SITE RECOMMENDATIONS: