

SITE SHEEP CREEK CABIN AHRS NO: ANC-110 ~~ANC-993~~ INHT NO: _____

OTHER SITE NAMES: _____ TRAIL SECTION:
 Seward-Rainy Pass _____
 Rainy Pass-Kaltag _____
 Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:
 Approximate _____ Actual _____
 Quad. ANC A-8
 Township 11N
 Range 3W
 Section 25
 Subsection _____
 Latitude: _____
 Longitude: _____

*See also
 Metchuk
 Cr Construction
 Camp.*

UTM REFERENCE:
 A _____
 Zone Easting Northing

LOCATION AND USE:

INSPECTED BY: _____ DATE: _____ Aerial _____ Onsite _____

STRUCTURAL TYPE: Shelter Structure _____ River Community _____
 Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED: _____ ORDER OF SIGNIFICANCE: _____

- _____ Site Protection
- _____ Preservation/Stabilization
- _____ Restoration
- _____ Reconstruction
- _____ Adaptive Reuse
- _____ National
- _____ Regional
- _____ Local

Estimated Treatment Costs _____
 Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- ___ Not Located
1 ___ No Remains
3 Ruin
8 ___ Poor (Roof In)
15 ___ Medium (Roof Intact)
25 ___ Good (Maintained)
40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
 Infrequent
___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
10 ___ Medium
5 Low

Total Points 98

STATEMENT OF SIGNIFICANCE:

REFERENCE:

SITE RECOMMENDATIONS: