

SITE J. NELSON'S CABIN

AHRS NO: _____

INHT NO: _____

OTHER SITE NAMES: _____

TRAIL SECTION:

Seward-Rainy Pass X
 Rainy Pass-Kaltag _____
 Kaltag-Nome _____

LAND STATUS: _____

LEGAL DESCRIPTION:

Approximate _____ Actual X
 Quad. ANCH. A-6
 Township 13N
 Range 3W
 Section 1
 Subsection SW 1/4 NW 1/4

Latitude: 61° 14'
 Longitude: 149° 44' 30"

UTM REFERENCE:

A _____
 Zone _____ Easting _____ Northing _____

LOCATION AND USE:

NORTH SIDE OF SHIP CREEK, APPROX 1 1/2 MILES FROM MOUTH OF SHIP CR.

INSPECTED BY: _____

DATE: _____

Aerial _____ Onsite _____

STRUCTURAL TYPE:

Shelter Structure _____ River Community _____
 Native Settlement _____ Mining Community _____ Other _____

WALLS:	IN	OUT	FLOOR	ROOF	CORNER NOTCH
Log-Rough	_____	_____	Dirt	Sod	Unknown
Log-Hewn	_____	_____	Wood	Metal	_____
Frame	_____	_____	Other	Wd. Plank	_____
Drop Siding	_____	_____	Unknown	Wd. Shingle	_____
Wall Covering	_____	_____		Tar Paper	_____
Unknown	_____	_____		Unknown	_____

TREATMENT RECOMMENDED:

ORDER OF SIGNIFICANCE:

_____ Site Protection
 _____ Preservation/Stabilization
 _____ Restoration
 _____ Reconstruction
 _____ Adaptive Reuse

_____ National
 _____ Regional
 _____ Local

Estimated Treatment Costs _____
 Estimated Planning/Research Costs _____

IDITAROD TRAIL INVENTORY

SITE _____ AHRS NO: _____ INHT NO: _____

MANAGEMENT RATING CRITERIA

ACCESS ----- 40 POINTS

- 5 ___ Difficult
(Dog Sled, Snow Mach., Heli.)
20 ___ Medium
(1 Day Hike, Boat, Fixed-Wing)
40 High
(Auto/Road, Short Hike)

CONDITION ----- 40 POINTS

- Not Located
1 ___ No Remains
3 ___ Ruin
8 ___ Poor (Roof In)
15 ___ Medium (Roof Intact)
25 ___ Good (Maintained)
40 ___ Restored

PRESENT VISITOR USE

- ___ Frequent
 Infrequent
___ None

POTENTIAL VISITOR USE--20 POINTS

- 20 ___ High
10 Medium
5 ___ Low

Total Points 50

STATEMENT OF SIGNIFICANCE:

REFERENCE:

GEN. LAND OFFICE PLST, DATED JULY 28, 1914, → LOCATES

SITE RECOMMENDATIONS: