SITE GALENA	AHRS NO:	NUL-006	INHT NO:	
OTHER SITE NAMES:	Rain	CTION: ard-Rainy Pass ny Pass-Kaltag tag-Nome		α 2
LAND STATUS: ADP 3/9/81 pm  TEO Plw; ADS;  TOWNS(TE TTEE  VILLAGE WD  SCHARGE WD  Actual  Quad.  Township  Range  Section  Subsection				TNTT
Latitude: Longitude:  UTM REFERENCE: A Zone Easting LOCATION AND USE:  INSPECTED BY:	Northing DATE:		Ons	Fite
STRUCTURAL TYPE: Shelter Stru	ucture	River Com	*.	
Native Settlement Mini	ing Commun	ity Oth	er	
WALLS: IN OUT FLOOF Log-Rough	rt	ROOF Sod Metal Wd. Plank Wd. Shingle Tar Paper Unknown	Unkı	R NOTCH Common C
TREATMENT RECOMMENDED:	ORDE	R OF SIGNIFICA	NCE:	
Site Protection Preservation/Stabilization Restoration Reconstruction Adaptive Reuse	on	National Regional Local		
Estimated Treatment Costs Estimated Planning/Research Co	osts			

SITE	AHRS NO:	INHT NO:
MANAGEMENT RATING CRITERIA		
ACCESS 40 POINTS		
5 Difficult		
(Dog Sled, Snow Mach., Heli.)		
20 Medium		
(1 Day Hike, Boat, Fixed-Wing)		
40 X High		
(Auto/Road, Short Hike)		
CONDITION 40 POINTS		
Not Located		
1 No Remains		
3 Ruin		
8 Poor (Roof In) UNKNOWN		
15 Medium (Roof Intact)		
25 Good (Maintained)		
40 Restored		
PRESENT VISITOR USE		
Frequent		
X Infrequent		
None		
POTENTIAL VISITOR USE20 POINTS		
20High		
10 Y Medium		
5Low		
50		
Total Points 20		

## STATEMENT OF SIGNIFICANCE:

## REFERENCE:

## SITE RECOMMENDATIONS: