3.12-9 AFFECTED ENVIRONMENT




FIGURE 3.12-3 Wind Roses for Six National Weather Service Stations along the TAPS ROW and at Prudhoe Bay (Source: NCDC 2001b; SECOR 1995)